



DX59FKZ


report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER
Colour	Grey
Year of manufacture	2009
Gearbox	-

Engine & fuel consumption

Engine capacity	2.488 cc
Fuel type	Diesel
CO2 emission	264 g/km
CO2 label	M





Internet history

Entry 1

Date	2022-07-15
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	24
Total items failed	1

MOT #18	2023-08-07 14:38
MOT test number	237847477270
Result	✓ Passed
Next expiry date	2024-08-16
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2023-08-07 07:35
MOT test number	746799366700
Result	✗ Failed
MAJOR	Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2022-08-17 14:35
MOT test number	402476481549
Result	✓ Passed

**MOT #15** 2022-08-16 15:35**MOT test number** 251976268460**Result** ✗ Failed**MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #14** 2021-11-05 15:17**MOT test number** 894782355696**Result** ✓ Passed**MOT #13** 2021-10-25 09:50**MOT test number** 638517937094**Result** ✗ Failed**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #12** 2020-10-01 11:20**MOT test number** 810339254034**Result** ✓ Passed**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #11** 2019-10-28 11:59**MOT test number** 592493438218**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt Child seats fitted in all rear seats**MOT #10** 2019-10-28 10:34**MOT test number** 185955933480**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt Child seats fitted in all rear seats**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Windscreen washer not working (3.5 (a))**MOT #9** 2018-09-15 10:26**MOT test number** 596701968289**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt child seats fitted in rear**MOT #8** 2018-09-14 15:57**MOT test number** 409075156445**Result** ✗ Failed**MAJOR** Offside Windscreen washer not working (3.5 (a))**Advice** Child Seat fitted not allowing full inspection of adult belt child seats fitted in rear**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #7** 2017-09-26 09:28**MOT test number** 652429016322**Result** ✓ Passed

**MOT #6** 2016-09-20 16:58**MOT test number** 660548217919**Result** ✓ Passed**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #5** 2015-09-15 12:32**MOT test number** 702299991336**Result** ✓ Passed**MOT #4** 2014-09-25 10:11**MOT test number** 837738664248**Result** ✓ Passed**MOT #3** 2014-09-24 09:07**MOT test number** 595237264294**Result** ✗ Failed**Advice** Offside Front Shock absorber has a slightly worn bush (2.7.4)**Fail** Nearside Front Shock absorber has an excessively worn bush (2.7.4)**MOT #2** 2013-09-26 10:27**MOT test number** 445179063281**Result** ✓ Passed**Notice** Offside hand brake requires attention**MOT #1** 2012-09-27 10:20**MOT test number** 248631872241**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
16 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	DX59FKZ
Plate since	2019-03-29
Current registration	DX59FKZ
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-10-07
Last registration	2023-08-07
Complete history	See info



Registration #1	2009-10-07	24 mi
Registration #2	2012-09-27	19.999 mi
Registration #3	2013-09-26	26.493 mi
Registration #4	2014-09-24	33.027 mi
Registration #5	2014-09-25	33.028 mi
Registration #6	2015-09-15	39.933 mi
Registration #7	2016-09-20	49.343 mi
Registration #8	2017-09-26	56.803 mi
Registration #9	2018-09-14	64.597 mi
Registration #10	2018-09-15	64.597 mi
Registration #11	2019-09-20	72.557 mi
Registration #12	2019-09-20	72.557 mi
Registration #13	2019-09-20	72.557 mi
Registration #14	2019-09-20	72.557 mi
Registration #15	2019-09-20	72.557 mi
Registration #16	2019-09-20	72.557 mi
Registration #17	2019-09-20	72.557 mi
Registration #18	2019-09-20	72.557 mi
Registration #19	2019-09-20	72.557 mi
Registration #20	2019-09-20	72.557 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Number of seats 7

Engine number NOT KNOWN