



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D2 R-DESIGN NAV
Colour	Grey
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-07
Pictures	23
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-07
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	4
Total items failed	4

MOT #9	2023-07-04 12:31
MOT test number	995139324801
Result	✓ Passed
Next expiry date	2024-07-07
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2022-06-22 11:43
MOT test number	118341294771
Result	✓ Passed

MOT #7	2022-06-22 08:36
MOT test number	719236150077
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #6	2021-07-08 08:21
MOT test number	426696868616
Result	✓ Passed

**MOT #5** 2021-07-08 08:21**MOT test number** 900257249914**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2020-08-25 15:14**MOT test number** 567150182148**Result** ✓ Passed**MOT #3** 2020-08-24 08:17**MOT test number** 741833037026**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-08-22 15:32**MOT test number** 335757599645**Result** ✓ Passed**MOT #1** 2018-08-14 11:56**MOT test number** 875435444727**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
7 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	7 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LF65XXB
Plate since	2019-03-29
Current registration	LF65XXB
Plate since	2019-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-13
Last registration	2023-07-04
Complete history	<a href="#">See info</a>



Registration #1	2015-09-13	24 mi
Registration #2	2018-08-14	47.228 mi
Registration #3	2019-08-22	64.239 mi
Registration #4	2020-08-24	75.352 mi
Registration #5	2020-08-25	75.352 mi
Registration #6	2020-08-25	75.352 mi
Registration #7	2020-08-25	75.352 mi
Registration #8	2020-08-25	75.352 mi
Registration #9	2020-08-25	75.352 mi
Registration #10	2020-08-25	75.352 mi
Registration #11	2020-08-25	75.352 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1463 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1206934
---------------	---------