





### General information

Make	VOLKSWAGEN
Model	BEETLE 60S EDITION
Colour	Blue
Year of manufacture	2013
Top speed	128 mph
0 - 100 km/h	8.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	118 kW / 161 HP / 158 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G







# Internet history


Entry 1

Date Pictures 2021-07-11

50

Listing price

View report



source: autotrader.co.uk



### MOT history

MOT expiry date	2024-08-30
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #10	2023-08-25 08:46
MOT test number	610485875516
Result	✓ Passed
Next expiry date 2024-08-3	
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #9	2022-08-20 09:16
MOT test number	723791632536
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

MOT #8	2021-08-31 12:19
MOT test number	204153062007
Result	✓ Passed





MOT #7	2021-08-30 10:21	
MOT test number	391335149462	
Result	🗙 Failed	
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))		
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or li (b) (i))	ght sources (4.7.1	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #6	2020-12-16 11:54
MOT test number	799994886517
Result	✓ Passed

MOT #5	2019-05-01 09:20
MOT test number	221690772336
Result	✓ Passed

MOT #4	2018-05-05 08:28
MOT test number	479015691372
Result	✓ Passed
Advice Windscreen has damage to an area less than a 40mm circle outside	de zone 'A' (8.3.1d)

MOT #3	2017-05-12	16:04
MOT test i	<b>number</b> 2401172	03554
Result	🗸 F	Passed
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	





MOT #2		2017-04-12 09:02
MOT test	number	702996326172
Result		✓ Passed
<b>Advice</b> (8.3.1d)	Nearside Front Lower Windscreen has damage to an area less than	a 40mm circle outside zone 'A'
MOT #1		2016-05-13 09:22
MOT test	number	503659136071
Result		✓ Passed
Advice	Nearside Front tyre wearing inside edge	
Advice	Nearside Rear wearing inside edge	

Advice	Offside Front wearing inside edge



Tax & MOT check

√ Taxed	√ мот
Tax due: 1 March 2025	Expires: 30 August 2024
Tax status	Valid until 1 March
Days left	305
MOT expiry date	30 August 2024
Full MOT history	<u>See MOT history</u>

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

********	
**********	
ANALY AND A ANALY	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-03
Last registration	2023-08-25
Complete history	See info



Registration #1	2013-05-03	19 mi
Registration #2	2016-05-13	1.936 mi
Registration #3	2017-04-12	59.211 mi
Registration #4	2017-05-12	60.626 mi
Registration #5	2018-05-05	68.326 mi
Registration #6	2019-05-01	74.815 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.117 esi
Registration #11		11.117 esi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight		
Width	2021 mm	
Height	1473 mm	
Length	4278 mm	
Wheel base	2540 mm	
Kerb weight	1454 kg	
Max. allowed weight	1830 kg	
Additional information		
Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	2	
CarCheck.co.uk		page 12/12

Number of seats	4
Number of axles	2
Engine number	CTHD040034