





report date: 2024-03-28

#### General information

Make	NISSAN
Model	PRIMASTAR SE LWB 115DCI SHR P/V
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
CO2 emission	198 g/km
CO2 label	J



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2021-10-30

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-24
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	15
Total items failed	13

MOT #13	2023-09-25 13:22
MOT test number	278610417712
Result	✓ Passed
Next expiry date	2024-09-24

MOT #12	2023-09-14 13:32	
MOT test number	720797198758	
Result	<b>X</b> Failed	
Fail Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))		
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))		
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		

MOT #11	2022-09-06 11:08
MOT test number	677047017744
Result	✓ Passed
MOT #10	2021-08-10 10:53
MOT test number	177066607345
Result	✓ Passed
Minor Hazard warning switch faulty (4.4.2 (a) (i))	

CarCheck.co.uk page 3/13



**BN64WJL** 

report date: 2024-03-28

**MOT** #9 2021-08-06 08:50 **MOT** test number 162394015072 Result × Failed Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Minor Hazard warning switch faulty (4.4.2 (a) (i)) Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail **Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Fail Front Registration plate missing (0.1 (a))

MOT #8

MOT test number

390668089472

Result

✓ Passed

MOT test number

Result

Fail Position lamp not working both front side lights (4.2.1 (a) (ii))

Fail Nearside Position lamp not working dip beam (4.2.1 (a) (ii))

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

CarCheck.co.uk page 4/13



**BN64WJL** 

report date: 2024-03-28

MOT test number

Result

Advice Nearside Front fog lense damaged

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2019-07-27 10:46 **MOT** test number 532563136309 Result × Failed **Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Nearside Front fog lense damaged **Advice Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail

MOT #4

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number
905177359594

Result

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/13



MOT #2

MOT test number

614941280890

Result

MOT #1

2017-08-05 07:42

MOT test number

546706649461

Result

Fail

Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax expired: 29 February 2024

# ✓ MOT

Expires: 24 September 2024

Tax status Expired at 29 February 2024

Days left 59 days too late

MOT expiry date 24 September 2024

Full MOT history See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-30
Last registration	2023-09-25
Complete history	See info



Registration #1	2014-09-30	8 mi
Registration #2	2017-08-05	37.485 mi
Registration #3	2017-08-05	37.485 mi
Registration #4	2018-08-01	52.759 mi
Registration #5	2018-08-01	52.759 mi
Registration #6	2019-07-27	67.100 mi
Registration #7	2019-07-28	67.100 mi
Registration #8	2020-08-21	77.116 mi
Registration #9		11.777 66
Registration #10		77,777 46
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		D.777 es
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 12/13




Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	146427

CarCheck.co.uk page 13/13