



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SPORT
Colour	White
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H



**MOT history**

MOT expiry date	2021-01-05
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	25
Total items failed	2

MOT #12	2020-01-06 17:17
----------------	------------------

MOT test number	709813527727
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2021-01-05
-------------------------	------------

- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front exhaust flexi worn
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2020-01-03 16:47

MOT test number

804194593065

Result**✗ Failed**

- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Front exhaust flexi worn
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

2018-12-12 13:09

MOT test number

660856474981

Result**✓ Passed****MOT #9**

2018-04-05 16:44

MOT test number

201209848480

Result**✓ Passed**

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Rear bush (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit Inner edge (4.1.E.1)

**MOT #8** 2017-04-04 08:38**MOT test number** 120297099331**Result** ✓ Passed**MOT #7** 2017-04-04 08:38**MOT test number** 295284490175**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-04-06 09:38**MOT test number** 862912938985**Result** ✓ Passed**MOT #5** 2015-04-13 13:27**MOT test number** 668243805192**Result** ✓ Passed**Notice** DRIVERS DOOR STRAP LOOSE**MOT #4** 2015-04-13 13:27**MOT test number** 997043105127**Result** ✗ Failed**Notice** DRIVERS DOOR STRAP LOOSE**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)



MOT #3	2014-04-05 10:05
MOT test number	228435394057
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	All tyres worn on inside edges
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-04-12 13:03
MOT test number	458422103146
Result	✓ Passed

MOT #1	2012-04-18 13:50
MOT test number	505389302120
Result	✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
13 November 2020

×

MOT

Expired:
5 January 2021

Tax status

Expired at 13 November 2020

Days left

1263 days too late

MOT expiry date

5 January 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	PK09JXE
Plate since	2024-03-29
Current registration	PK09JXE
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-04-18
Last registration	2020-01-06
Complete history	See info



Registration #1	2009-04-18	27 mi
Registration #2	2012-04-18	25.540 mi
Registration #3	2013-04-12	28.875 mi
Registration #4	2014-04-05	40.581 mi
Registration #5	2015-04-13	56.337 mi
Registration #6	2016-04-06	69.141 mi
Registration #7	2019-05-20	75.277 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number	156670
---------------	--------