





General information

Make	HONDA
Model	INSIGHT IMA HE
Colour	Silver
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	65.7 mpg
Consumption extra urban	70.6 mpg
Consumption combined	68.9 mpg
CO2 emission	96 g/km
CO2 label	A







MOT history

MOT expiry date	2021-07-20
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	7
Total items failed	4

MOT #14	2020-07-21 13:30
MOT test number	667088202177
Result	✓ Passed
Next expiry date	2021-07-20

MOT #13	2020-01-25 12:26
MOT test number	85132222816
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #12		2020-01-25 12:26
MOT test number		910659216559
Result		🗙 Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	





MOT #11	2019-07-26 16:49
MOT test number	304230900762
Result	✓ Passed
AdviceOffside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))AdviceNearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #10	2019-01-28 12:14
MOT test number	136572742683
Result	✓ Passed

МОТ #9	2018-07-30 12:38
MOT test number	675650459962
Result	🗸 Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened b	ooth side (1.1.14 (a) (ii))

MOT #8	2018-01-23 11:31
MOT test number	808372218719
Result	✓ Passed

MOT #7	2018-01-23 07:55
MOT test number	528021428471
Result	🗙 Failed
Fail Registration plate lamp not working (1.1.C.1d)	

2018-01-22 11:36
223005124232
✓ Passed





MOT #5	2018-01-22 11:36
MOT test number	192718840273
Result	× Failed
Pass with rectificationNearside Front Front position lamp(s) not working (1.1.A.3b)	
MOT #4	2017-01-20 10:28
MOT test number	187184952065
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Rear brake fluctuating, but not excessively (3.7.B.3)	
MOT #3	2016-03-08 13:35
MOT test number	253079577135
Result	✓ Passed
MOT #2	2015-09-09 15:53
MOT test number	139057678497
Result	✓ Passed
MOT #1	2015-04-08 14:40
MOT test number	315358795062
Result	✓ Passed





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plate	25.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-01
Last registration	2020-07-21
Complete history	See info



Registration #1	2012-03-01	7 mi
Registration #2	2015-04-08	18.421 mi
Registration #3	2015-09-09	20.143 mi
Registration #4	2016-03-08	31.818 mi
Registration #5	2017-01-20	39.316 mi
Registration #6	2018-01-22	78.211 mi
Registration #7	2018-01-22	78.211 mi
Registration #8	2018-01-23	78.302 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight	
Width	1695 mm
Height	1435 mm
Length	4395 mm
Wheel base	2545 mm
Kerb weight	1243 kg
Additional information	
Additional information Fuel tank capacity	40 I
	40 I Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5