



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	BOXER BLUE HDI 435 L4H2 PROFESSIONAL P/V
Colour	White
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-05
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-24
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #5	2023-09-25 16:13
MOT test number	974962055474
Result	✓ Passed
Next expiry date	2024-09-24
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Suspension arm ball joint has slight play n\s off\s front (5.3.4 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #4	2022-09-14 09:31
MOT test number	919111589286
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge N/s off/s front (5.2.3 (e))
Advice	Front Play in steering rack inner joint(s) N/s off/s front
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #3**

2022-09-14 09:31

MOT test number

377761817751

Result**✗ Failed****Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Tyre worn close to legal limit/worn on edge N/s off/s front (5.2.3 (e))**Advice** Front Play in steering rack inner joint(s) N/s off/s front**MOT #2**

2021-09-25 14:30

MOT test number

828960238116

Result**✓ Passed****MOT #1**

2021-09-21 09:06

MOT test number

640154589235

Result**✗ Failed****Fail** Nearside Front Daytime running lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-08-09
Last registration	2023-09-25
Complete history	See info



Registration #1	2018-08-09	28 mi
Registration #2	2019-09-21	74.363 mi
Registration #3	2021-09-21	74.363 mi
Registration #4	2021-09-25	74.363 mi
Registration #5	2023-09-25	74.363 mi
Registration #6	2023-09-25	74.363 mi
Registration #7	2023-09-25	74.363 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	DYZZ4178236