





report date: 2024-03-29

General information

Make	AUDI
Model	A4 AVANT TDI DPF S LINE
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-09

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



PX59YNO report date: 2024-03-29

MOT history

MOT expiry date	2025-02-21
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	9

MOT #17		2024-02-21 19:09
MOT test	number	168180151014
Result		✓ Passed
Next expi	ry date	2025-02-21
Advice	Engine covers And Undertrays fitted obscuring some components	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Upper Suspension arm damaged but not seriously weakened (5.	3.3 (b) (i))
Advice	Offside Front Side mirror casing slightly damaged	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16		2023-02-22 16:41
MOT test	number	133974395224
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3	B (e))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorate	ed (6.1.7 (g) (i))
Advice	Under trays fitted	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	14 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #15 2023-02-20 17:15

MOT test number 562758772472

Result X Failed

Advice Under trays fitted

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14 2021-12-20 12:42

MOT test number 744558497737

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13 2021-12-17 14:18

MOT test number 901230740633

Result X Failed

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2021-01-05 15:43

MOT test number 204330598141

Result ✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement forward (5.3.4 (a) (i))

MOT #11 2020-01-16 15:40

MOT test number 564280057551

Result \(\sqrt{Passed} \)

MOT #10 2020-01-10 16:17

MOT test number 175631451032

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm 245/45/17 (5.2.3 (e))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm 245/45/17 (5.2.3 (e))

Fail Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9 2019-01-10 13:55

MOT test number 127729679275

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))

MOT #8 2018-01-12 08:36

MOT test number 317691164046

Result \rightarrow Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Front discs worn

Fail Offside Front Mechanical brake component has restricted free movement (3.5.1k)

 MOT #6
 2017-01-12 16:31

 MOT test number
 191464848982

 Result
 ✓ Passed

MOT test number

Result

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2015-09-23 09:27
MOT test number 953147454833
Result ✓ Passed

MOT #3

MOT test number

Result

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 6/14



report date: 2024-03-29



MOT #1	2012-09-10 09:15
MOT test number	385424752211
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check





Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

e which misterly	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 11/14



PX59YNO report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



PX59YNO report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-30
Last registration	2024-02-21
Complete history	See info



Registration #1	2009-09-30	24 mi
Registration #2	2012-09-10	26.074 mi
Registration #3	2013-09-19	34.434 mi
Registration #4	2014-09-19	43.022 mi
Registration #5	2015-09-23	49.617 mi
Registration #6	2016-09-20	56.949 mi
Registration #7	2017-01-12	57.440 mi
Registration #8	2018-01-11	74.446 mi
Registration #9	2018-01-12	74.446 mi
Registration #10	2019-01-10	99.889 mi
Registration #10 Registration #11	2019-01-10	99.889 mi
	2019-01-10	99.889 mi
Registration #11	2019-01-10	99.889 mi
Registration #11 Registration #12	2019-01-10	99.889 mi
Registration #11 Registration #12 Registration #13	2019-01-10	99.889 mi
Registration #11 Registration #12 Registration #13 Registration #14	2019-01-10	99.889 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2019-01-10	99.889 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2019-01-10	99.889 mi

More info >

CarCheck.co.uk page 13/14



PX59YNO report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1436 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1520 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number CAG 268091