





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM X SPORT TDCI
Colour	Silver
Year of manufacture	-
Top speed	139 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

MOT history

MOT #14 2021-01-28 11:52

MOT test number 913774563838

Result ✓ Passed

Next expiry date 2022-01-27

Advice Macpherson strut pin or bush worn but not resulting in excessive movement 2x front top strut bearings (5.3.4 (a) (i))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13 2021-01-27 14:08

MOT test number 958883212219

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Macpherson strut pin or bush worn but not resulting in excessive movement 2x front top strut bearings (5.3.4 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #12 2020-01-21 15:04

MOT test number 234564460282

Result ✓ Passed

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT test number

Result

Advice
Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice
Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice
Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10 2019-02-27 11:28 **MOT** test number 187853144261 Result × Failed Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i)) Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i)) Fail Nearside Front Road wheel fixings not compatible (5.2.2 (d)) Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (5.2.3 (d) (i)) **Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords and below limit (5.2.3 (d) (i)) Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Oil leak

Advice Offside Rear tyre wearing low

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2018-02-20 12:59 **MOT** test number 934220983738 Result × Failed **Advice** Oil leak Fail Offside Rear Radius arm rubber bush deteriorated resulting in excessive movement front bush (2.4.G.2)Fail Nearside Rear Rear wheel bearing rough when rotated (2.6.1) Fail Nearside Rear Radius arm rubber bush deteriorated resulting in excessive movement front bush (2.4.G.2)Advice Offside Rear tyre wearing low **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7

2017-02-20 12:15

MOT test number

894039465916

Result

✓ Passed

Advice

N/s/f tyre worn very close to legal limit advise to change asap

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6		2016-02-15 10:30
MOT test	number	650766452847
Result		✓ Passed
Advice	Brake discs slightly pitted	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2015-04-11 09:34
MOT test number	279201905191
Result	✓ Passed
Notice Some rusting and lipped front brake discs	

MOT #4		2014-04-17 16:38
MOT test	number	395627104135
Result		✓ Passed
Notice	Both rear tyres worn to 2/3mm	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

MOT #3		2013-04-24 15:45
MOT test	number	235054213162
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Both front tyres treads getting low 3mm	

CarCheck.co.uk page 5/12



report date: 2024-03-29

 MOT #2
 2012-09-18 16:46

 MOT test number
 618312362233

 Result
 ✓ Passed

 MOT #1
 2012-04-17 09:39

 MOT test number
 547038702154

 Result
 ✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim	1410	00	hi	~ +	00
U	wı	ıer		รเ	on

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
HARMAN CONTRACTOR CONT	

	More info >
Plate changes	
Coo in this shook if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-04-25
Last registration	2021-01-28
Complete history	See info



Registration #1	2009-04-25	21 mi
Registration #2	2012-04-17	43.222 mi
Registration #3	2012-09-18	50.728 mi
Registration #4	2013-04-24	57.990 mi
Registration #5	2014-04-17	69.181 mi
Registration #6	2015-04-11	85.267 mi
Registration #7	2016-02-15	92.609 mi
Registration #8	2017-02-20	105.161 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1570 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 9U48397