



RENAULT

HJ65YNY

report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | RENAULT |
| Model | ZOE DYNAMIQUE NAV |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 84 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| | |
|-------------|---------------------|
| Power | 91 BHP |
| Max. torque | 220 Nm at 2.500 rpm |
| Fuel type | Electricity |





LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-11 |
| Pictures | 8 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-28 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 6 |

| | |
|------------------|---|
| MOT #8 | 2023-11-23 15:19 |
| MOT test number | 676224465066 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-28 |
| Advice | Offside Front Suspension arm ball joint has slight play Lower arm (5.3.4 (a) (i)) |

| | |
|-----------------|--|
| MOT #7 | 2022-11-24 11:51 |
| MOT test number | 152191191736 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |

| | |
|-------------------------|--|
| MOT #6 | 2022-11-24 11:51 |
| MOT test number | 632342800626 |
| Result | ✗ Failed |
| Pass with rectification | Offside Rear Direction indicator incorrect colour (4.4.3 (a)) |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Pass with rectification | Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) |
| Pass with rectification | Nearside Rear Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii)) |

**MOT #5** 2021-11-25 11:05**MOT test number** 771192130900**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Stone chip in windscreen**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-10-29 14:45**MOT test number** 884503675101**Result** ✓ Passed**MOT #3** 2020-10-29 14:45**MOT test number** 630539924438**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Pass with rectification** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #2** 2019-11-29 09:00**MOT test number** 215397440098**Result** ✓ Passed**MOT #1** 2018-11-20 16:42**MOT test number** 687556620276**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
28 November 2024

| | |
|-------------------|-------------------------|
| Tax status | Valid until 1 September |
|-------------------|-------------------------|

| | |
|------------------|-----|
| Days left | 126 |
|------------------|-----|

| | |
|------------------------|------------------|
| MOT expiry date | 28 November 2024 |
|------------------------|------------------|

| | |
|-------------------------|---------------------------------|
| Full MOT history | See MOT history |
|-------------------------|---------------------------------|



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,000 |
| Auction value | £ 15,000 |
| Average private trade value | £ 15,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-28 |
| Current registration | |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2015-11-24 |
| Last registration | 2023-11-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-11-24 | 10 mi |
| Registration #2 | 2018-11-20 | 29.780 mi |
| Registration #3 | 2019-11-29 | 44.924 mi |
| Registration #4 | 2020-10-29 | 64.930 mi |
| Registration #5 | 2020-10-29 | 64.930 mi |
| Registration #6 | 2020-10-29 | 64.930 mi |
| Registration #7 | 2020-10-29 | 64.930 mi |
| Registration #8 | 2020-10-29 | 64.930 mi |
| Registration #9 | 2020-10-29 | 64.930 mi |
| Registration #10 | 2020-10-29 | 64.930 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 80% |
| Pedestrian | 66% |
| Safety systems | 85% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1730 mm |
| Height | 1562 mm |
| Length | 4084 mm |
| Wheel base | 2588 mm |
| Kerb weight | 1468 kg |
| Max. allowed weight | 1965 kg |

Additional information

| | |
|-----------------|----------------|
| Fuel delivery | Not Applicable |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

| | |
|---------------|---------|
| Engine number | C010924 |
|---------------|---------|