



FG09KYO

report date: 2024-03-29

General information

Make	SUZUKI
Model	SPLASH GLS PLUS
Colour	Turquoise
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	86 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	131 g/km
CO2 label	E






Internet history

Entry 2


Date	2023-01-04
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-03
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-15
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	43
Total items failed	6

MOT #182024-04-16 13:43

MOT test number281033699472

Result✓ Passed

Next expiry date2025-04-15

- Advice

Offside Front Brake pipe corroded, covered in grease or other material brake pipe to flexi (1.1.11 (c))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice

Rear Brake pipe corroded, covered in grease or other material n/s & o/s axle pipes (1.1.11 (c))
- Advice

Parking brake requirements only just met
- Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #17**

2024-04-08 12:47

MOT test number

803231774807

Result

✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Parking brake requirements only just met

Advice Rear Brake pipe corroded, covered in grease or other material n/s & o/s axle pipes (1.1.11 (c))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material brake pipe to flexi (1.1.11 (c))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16

2023-01-10 15:45

MOT test number

314868723439

Result

✓ Passed

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15

2022-06-25 11:13

MOT test number

257111097432

Result

✓ Passed

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Front Macpherson strut pin or bush worn but not resulting in excessive movement Both upper mountings (5.3.4 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))



MOT #14	2021-06-28 14:03
----------------	------------------

MOT test number	894996308572
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2020-12-21 11:20
----------------	------------------

MOT test number	328394594528
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2020-12-16 11:17
----------------	------------------

MOT test number	143810378526
------------------------	--------------

Result	✗ Failed
---------------	----------

MAJOR Central Rear Brake hose ferrule excessively corroded off side (1.1.12 (f) (i))

MAJOR Central Rear Outer Brake hose ferrule excessively corroded near side (1.1.12 (f) (i))

MOT #11	2019-04-17 15:41
----------------	------------------

MOT test number	163891776293
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2019-04-17 10:05**MOT test number** 940527706471**Result** ✗ Failed

- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2018-04-17 10:39**MOT test number** 198384893991**Result** ✓ Passed

Advice Parking brake requires attention

MOT #8 2017-04-11 10:28**MOT test number** 883111829025**Result** ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment Top mount (2.5.A.1c)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment Top mount (2.5.A.1c)

MOT #7 2016-04-19 08:43**MOT test number** 610978409192**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2016-04-18 13:47**MOT test number** 666038377378**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2015-04-15 17:01**MOT test number** 226235605470**Result** ✓ Passed**Notice** O/S/F tyre wearing on outer edge**MOT #4** 2015-04-15 12:10**MOT test number** 645165005114**Result** ✗ Failed**Fail** Offside Front Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Notice** O/S/F tyre wearing on outer edge**MOT #3** 2014-04-09 11:46**MOT test number** 108509994058**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Items removed from driver's view prior to test**Notice** Offside front wheel bearing noisy when rotated but not rough



MOT #2	2013-04-24 11:24
MOT test number	476424813131
Result	✓ Passed

MOT #1	2012-05-09 15:53
MOT test number	836760232197
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
15 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	FG09KYO
Plate since	2019-03-29
Current registration	FG09KYO
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-05-14
Last registration	2024-04-16
Complete history	See info



Registration #1	2009-05-14	7 mi
Registration #2	2012-05-09	30.910 mi
Registration #3	2013-04-24	34.058 mi
Registration #4	2014-04-09	37.279 mi
Registration #5	2015-04-15	41.355 mi
Registration #6	2015-04-15	41.355 mi
Registration #7	2016-04-18	46.182 mi
Registration #8	2016-04-19	46.182 mi
Registration #9	2017-04-11	52.605 mi
Registration #10	2018-04-17	59.046 mi
Registration #11	2019-04-17	65.123 mi
Registration #12	2020-04-17	71.200 mi
Registration #13	2021-04-17	77.277 mi
Registration #14	2022-04-17	83.354 mi
Registration #15	2023-04-17	89.431 mi
Registration #16	2024-04-16	95.508 mi
Registration #17	2025-04-16	101.585 mi
Registration #18	2026-04-16	107.662 mi
Registration #19	2027-04-16	113.739 mi
Registration #20	2028-04-16	119.816 mi
Registration #21	2029-04-16	125.893 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3715 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1045882