





report date: 2024-03-28

#### General information

Make	FIAT
Model	500X MULTIJET CROSS PLUS
Colour	Red
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

#### Internet history

#### Entry 1

Date 2021-11-19

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-01-03
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #6	2023-12-19 10:07
MOT test number	948366188894
Result	✓ Passed
Next expiry date	2025-01-03
Minor Nearside Front Track rod end ball join ingress of dirt (2.1.3 (g) (i))	nt dust cover damaged or deteriorated, but preventing the
Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice Tyre slightly damaged/cracking or p	perishing both rears (5.2.3 (d) (ii))

MOT #5	2022-12-21 09:18
MOT test number	978991439469
Result	<b>✓</b> Passed
MOT #4	2022-01-04 14:33
MOT test number	271652545360

MOT test number	2/1052545360
Result	✓ Passed
MOT #3	2021-11-08 11:14
MOT test number	247288634503
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))  Minor Windscreen damaged but not adversely affecting driver's view chipped (3.2)	(a) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice
(e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread also worn inner edge (5.2.3 (e))

Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm tread also worn inner edge (5.2.3 (e))

MOT #1

MOT test number

Result

Advice Steering column top bearing slightly worn (2.2.2 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

_			
<b>IWO</b>	nor.	hic	torv
	ıcı	шэ	ינטוי

For how long did the current and previous owner(s) have this FIAT? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	
**************************************	
2000000	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK ZIN
Plate since	
Current registration	UK SIP
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

### Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-11-25
Last registration	2023-12-19
Complete history	See info



Registration #1	2016-11-25	12 mi
Registration #2	2019-11-04	23.024 mi
Registration #3	2020-11-05	26.591 mi
Registration #4	2021-11-08	28.354 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



## Dimensions & weight

Width	1796 mm
Height	1608 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

## Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles 2

Engine number 7709347