



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI ALTITUDE
Colour	Black
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	172 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.0 mpg
CO2 emission	275 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-07-07
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	17
Total items failed	15

MOT #21 2023-06-20 07:48

MOT test number 876096170943

Result ✓ Passed

Next expiry date 2024-07-04

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #20 2022-07-01 16:56

MOT test number 465080785890

Result ✓ Passed

MOT #19 2022-06-25 08:22

MOT test number 256857542718

Result ✗ Failed

Fail Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Fail Offside Front Headlamp insecure (4.1.1 (c))

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Fail Nearside Front Headlamp insecure (4.1.1 (c))

**MOT #18** 2021-07-05 09:06**MOT test number** 506934200937**Result** ✓ Passed**Advice** Nearside Front tyre sidewall damage**MOT #17** 2021-07-02 10:36**MOT test number** 439255731087**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front tyre sidewall damage**MOT #16** 2020-06-05 10:03**MOT test number** 774913559491**Result** ✓ Passed**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2019-06-10 14:39**MOT test number** 879449495465**Result** ✓ Passed**MOT #14** 2019-02-14 16:11**MOT test number** 596621918607**Result** ✓ Passed

**MOT #13** 2019-02-14 11:25**MOT test number** 920572114775**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #12** 2018-02-16 11:57**MOT test number** 178553260429**Result** ✓ Passed**MOT #11** 2018-02-15 09:59**MOT test number** 924887338866**Result** ✗ Failed**Fail** Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)**MOT #10** 2017-02-16 09:25**MOT test number** 351142939171**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Both rear brake discs worn**MOT #9** 2016-02-25 11:51**MOT test number** 535350130238**Result** ✓ Passed

**MOT #8** 2016-02-25 10:19**MOT test number** 335918593231**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #7** 2015-02-19 11:40**MOT test number** 506130855074**Result** ✓ Passed**MOT #6** 2015-02-19 08:59**MOT test number** 797520055033**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2014-01-20 14:31**MOT test number** 187390824439**Result** ✓ Passed**MOT #4** 2014-01-20 09:18**MOT test number** 735310424050**Result** ✗ Failed**Fail** Offside Obligatory mirror seriously deteriorated, affecting the rear view (8.1.2a)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #3** 2012-08-03 08:50**MOT test number** 709666312233**Result** ✓ Passed



MOT #2	2012-08-03 08:50
MOT test number	776706812222
Result	✗ Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2011-08-02 12:45
MOT test number	257084111270
Result	✓ Passed
Notice	Both rear tyres getting low
Notice	Both front tyres nearing limit



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 July 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-01
Last registration	2023-06-20
Complete history	See info



Registration #1	2008-05-01	28 mi
Registration #2	2011-08-02	33.486 mi
Registration #3	2012-08-03	41.504 mi
Registration #4	2014-01-20	53.110 mi
Registration #5	2014-01-20	53.110 mi
Registration #6	2015-02-19	63.818 mi
Registration #7	2015-02-19	63.819 mi
Registration #8	2016-02-25	74.560 mi
Registration #9	2016-02-25	74.560 mi
Registration #10	2017-02-16	85.497 mi
Registration #11	2018-02-15	95.129 mi
Registration #12	2019-06-20	105.277 mi
Registration #13	2019-06-20	105.277 mi
Registration #14	2019-06-20	105.277 mi
Registration #15	2019-06-20	105.277 mi
Registration #16	2019-06-20	105.277 mi
Registration #17	2019-06-20	105.277 mi
Registration #18	2019-06-20	105.277 mi
Registration #19	2019-06-20	105.277 mi
Registration #20	2019-06-20	105.277 mi
Registration #21	2019-06-20	105.277 mi
Registration #22	2019-06-20	105.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2230 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2510 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats

5

Engine number

BPE 011351
