



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	Red
Year of manufacture	2013
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-20
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #11	2023-08-08 09:28
MOT test number	708983538184
Result	✓ Passed
Next expiry date	2024-08-07
Advice	Exhaust mounting defective (6.1.2 (a))

MOT #10	2022-08-04 13:47
MOT test number	246673847803
Result	✓ Passed

MOT #9	2022-08-04 10:18
MOT test number	846358816900
Result	✗ Failed
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #8	2021-07-31 11:06
MOT test number	815842687470
Result	✓ Passed

**MOT #7** 2021-05-14 09:53**MOT test number** 284849111677**Result** ✓ Passed**MOT #6** 2021-05-10 08:01**MOT test number** 478440470657**Result** ✗ Failed**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #5** 2020-06-01 07:46**MOT test number** 854495050596**Result** ✓ Passed**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #4** 2019-06-07 14:49**MOT test number** 399323835519**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear exhaust box slightly corroded**MOT #3** 2018-10-27 08:27**MOT test number** 747641467767**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))



MOT #2	2017-10-28 08:33
MOT test number	284991525744
Result	✓ Passed

MOT #1	2016-10-19 09:15
MOT test number	428563918925
Result	✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YR63YZW
Plate since	2019-09-29
Current registration	YR63YZW
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-31
Last registration	2023-08-08
Complete history	See info



Registration #1	2013-10-31	14 mi
Registration #2	2016-10-19	57.504 mi
Registration #3	2017-10-28	71.208 mi
Registration #4	2018-10-27	83.971 mi
Registration #5	2019-06-07	87.173 mi
Registration #6	2020-06-01	99.021 mi
Registration #7	2021-05-10	108.963 mi
Registration #8	2022-05-20	121.277 mi
Registration #9	2022-05-20	121.277 mi
Registration #10	2022-05-20	121.277 mi
Registration #11	2022-05-20	121.277 mi
Registration #12	2022-05-20	121.277 mi
Registration #13	2022-05-20	121.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	6942892