



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	White
Year of manufacture	2014
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-22
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-07
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	48
Total items failed	5

MOT #13	2023-09-08 14:08
MOT test number	129528268063
Result	✓ Passed
Next expiry date	2024-09-07

MOT #12	2023-09-05 18:58
MOT test number	605749413775
Result	✗ Failed
MAJOR Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))	
MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	

MOT #11	2023-02-06 15:55
MOT test number	759740545385
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

**MOT #10**

2023-01-28 09:58

MOT test number

104567218631

Result**✗ Failed**

- MAJOR** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #9

2022-05-13 08:08

MOT test number

996878830822

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2022-05-12 12:05**MOT test number** 683722128043**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-07-02 14:26**MOT test number** 970155473955**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2020-07-02 14:26

MOT test number

144744473703

Result**✗ Failed****Pass with rectification**

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification

Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #5

2019-05-11 10:49

MOT test number

631489556595

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor

Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2019-05-11 08:51**MOT test number** 136676515325**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2018-04-27 10:37**MOT test number** 297397398715**Result** ✓ Passed**Advice** Eml is on**MOT #2** 2018-04-27 10:37**MOT test number** 687732471900**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Eml is on



MOT #1	2017-05-17 11:00
MOT test number	436920049557
Result	✓ Passed
Advice	Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	DN64LCZ
Plate since	2019-03-28
Current registration	DN64LCZ
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-10-23
Last registration	2023-09-08
Complete history	See info



Registration #1	2014-10-23	18 mi
Registration #2	2017-05-17	36.087 mi
Registration #3	2018-04-27	60.865 mi
Registration #4	2018-04-27	60.865 mi
Registration #5	2019-05-11	88.107 mi
Registration #6	2019-05-11	88.107 mi
Registration #7	2020-07-02	108.565 mi
Registration #8	2020-07-02	108.565 mi
Registration #9	2020-07-02	108.565 mi
Registration #10	2020-07-02	108.565 mi
Registration #11	2020-07-02	108.565 mi
Registration #12	2020-07-02	108.565 mi
Registration #13	2020-07-02	108.565 mi
Registration #14	2020-07-02	108.565 mi
Registration #15	2020-07-02	108.565 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	78%
Pedestrian	61%
Safety systems	83%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Wheel base	2612 mm
Kerb weight	1390 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FJBS2032884