



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 URBAN LITE
Colour	Red
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-11
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-28
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	41
Total items failed	6

MOT #15	2023-08-29 14:07
MOT test number	218565819092
Result	✓ Passed
Next expiry date	2024-08-28

MOT #14	2022-08-05 13:52
MOT test number	602657030959
Result	✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread delaminated (been penned in !) [almost excessive] (0.1 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Brake pipe corroded, covered in grease or other material main at rear (1.1.11 (c))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material main at rear (1.1.11 (c))

**MOT #13**

2022-08-02 15:10

**MOT test number**

251361936206

**Result****✗ Failed****Advice** Offside Brake pipe corroded, covered in grease or other material main at rear (1.1.11 (c))**DANGEROUS** Nearside Front Coil spring mounting insecure to the extent that relative movement is visible strut lower spring mounting corroded through (5.3.1 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread delaminated (been panned in !) [almost excessive] (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm scrubbed both edges (5.2.3 (e))**MAJOR** Nearside Front Tyre not fitted in accordance with side wall instructions wrong direction (5.2.3 (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**DANGEROUS** Offside Front Coil spring mounting insecure to the extent that relative movement is visible strut lower spring mounting corroded through (5.3.1 (a) (ii))**Advice** Nearside Brake pipe corroded, covered in grease or other material main at rear (1.1.11 (c))**Advice** Tyre slightly damaged/cracking or perishing All 4X heavily perished (5.2.3 (d) (ii))**MAJOR** Nearside Front Tyre fouling a part of the vehicle rubbing on spring due to strut lower spring mount failure (5.2.3 (f))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm scrubbed both edges (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12**

2021-06-25 12:34

**MOT test number**

542152657661

**Result****✓ Passed**

**MOT #11** 2020-07-10 13:56**MOT test number** 368577527879**Result** ✓ Passed**Advice** Front tyres getting low**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources 1 x rear (4.7.1 (b) (i))**Advice** Nearside front tyre cracked and perished**Advice** Both main brake pipes covered in grease**MOT #10** 2020-07-10 08:32**MOT test number** 800906807109**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside front tyre cracked and perished**Advice** Both main brake pipes covered in grease**MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Front tyres getting low**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources 1 x rear (4.7.1 (b) (i))**MOT #9** 2019-03-22 16:49**MOT test number** 590646282776**Result** ✓ Passed**Advice** Offside front wheel slightly damaged**Advice** Brake pipe corroded, covered in grease or other material both main brake pipes covered in grease (1.1.11 (c))**Advice** Nearside rear tyre getting low

**MOT #8** 2019-03-22 15:16**MOT test number** 609615930036**Result** ✗ Failed**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside rear tyre getting low**Advice** Offside front wheel slightly damaged**Advice** Brake pipe corroded, covered in grease or other material both main brake pipes covered in grease (1.1.11 (c))**MOT #7** 2018-03-18 11:07**MOT test number** 597370335589**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**MOT #6** 2017-03-25 13:07**MOT test number** 250740396477**Result** ✓ Passed**MOT #5** 2017-03-25 11:31**MOT test number** 289102962757**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit tread cracked and perished (4.1.E.1)**Advice** Rear silencer exhaust hanger deteriorated and ready to break**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #4** 2016-02-02 19:07**MOT test number** 144052240149**Result** ✓ Passed**MOT #3** 2016-01-29 15:19**MOT test number** 863898644547**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-02-03 09:25**MOT test number** 277484235022**Result** ✓ Passed**MOT #1** 2014-02-25 08:45**MOT test number** 867866454011**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
28 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	28 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>FD60VUU</b>
Plate since	2019-03-29
Current registration	<b>FD60VUU</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-02-23
Last registration	2023-08-29
Complete history	<a href="#">See info</a>



Registration #1	2011-02-23	24 mi
Registration #2	2014-02-25	20.764 mi
Registration #3	2015-02-03	26.201 mi
Registration #4	2016-01-29	42.873 mi
Registration #5	2016-02-02	43.084 mi
Registration #6	2017-03-25	58.618 mi
Registration #7	2017-03-25	58.618 mi
Registration #8	2018-03-18	62.023 mi
Registration #9	2019-03-22	68.164 mi
Registration #10	2019-03-22	68.164 mi
Registration #11	2019-03-22	68.164 mi
Registration #12	2019-03-22	68.164 mi
Registration #13	2019-03-22	68.164 mi
Registration #14	2019-03-22	68.164 mi
Registration #15	2019-03-22	68.164 mi
Registration #16	2019-03-22	68.164 mi
Registration #17	2019-03-22	68.164 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7010031