




report date: 2024-03-29

General information

Make	JAGUAR
Model	XKR
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	420 BHP
Max. torque	560 Nm at 4.000 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.8 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	294 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-10-17
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	16
Total items failed	8

MOT #20	2023-10-11 07:23
MOT test number	773559590105
Result	✓ Passed
Next expiry date	2024-10-10

MOT #19	2023-01-27 12:05
MOT test number	992968071971
Result	✓ Passed

MOT #18	2022-03-23 16:40
MOT test number	820713484395
Result	✓ Passed

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both front suspension arms have slight play (5.3.4 (a) (i))

**MOT #17** 2022-03-23 12:15**MOT test number** 100605163954**Result** ✗ Failed**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both discs (1.1.14 (a) (ii))**MAJOR** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front suspension arms have slight play (5.3.4 (a) (i))**MAJOR** Rear Registration plate does not conform to the specified requirements (0.1 (d))**MOT #16** 2021-03-16 12:31**MOT test number** 118207763171**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2020-03-12 12:29**MOT test number** 666314780496**Result** ✓ Passed**MOT #14** 2019-03-25 11:15**MOT test number** 891354485306**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2018-03-26 10:06**MOT test number** 401144903882**Result** ✓ Passed

**MOT #12** 2017-02-10 13:11**MOT test number** 573135324720**Result** ✓ Passed**MOT #11** 2016-06-24 14:20**MOT test number** 153926049937**Result** ✓ Passed**MOT #10** 2015-10-21 13:40**MOT test number** 444976707457**Result** ✓ Passed**MOT #9** 2014-10-15 11:10**MOT test number** 547138584289**Result** ✓ Passed**MOT #8** 2014-10-15 11:10**MOT test number** 978978884257**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #7** 2013-10-10 13:50**MOT test number** 867723083255**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-10-10 11:35**MOT test number** 778283083213**Result** ✗ Failed**Fail** Offside Front Brake hose has insufficient room to move, resulting in fouling on any part (3.6.B.4a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-10-08 13:38**MOT test number** 608862782221**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #4** 2011-10-14 16:10**MOT test number** 387457581484**Result** ✓ Passed**MOT #3** 2011-10-14 16:10**MOT test number** 366367281262**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #2** 2010-10-05 15:44**MOT test number** 231988870255**Result** ✓ Passed



MOT #12010-10-04 11:56

MOT test number174967470274

ResultX Failed

- Pass with rectification

Nearside Headlamp aim too low (1.8)
- Fail

Nearside Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Pass with rectification

Offside Headlamp aim too low (1.8)
- Notice

Off Side Front Outer tyre wall has a cut in excess of 25mm but no cords or belt exposed.



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-29
Current registration	 XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-11
Last registration	2023-10-11
Complete history	See info



Registration #1	2007-10-11	15 mi
Registration #2	2010-10-04	12.373 mi
Registration #3	2010-10-05	12.374 mi
Registration #4	2011-10-14	15.350 mi
Registration #5	2012-10-08	16.419 mi
Registration #6	2013-10-10	20.301 mi
Registration #7	2013-10-10	20.301 mi
Registration #8	2014-10-15	25.949 mi
Registration #9	2015-10-21	35.252 mi
Registration #10	2016-06-24	39.633 mi
Registration #11	2016-06-24	39.633 mi
Registration #12	2016-06-24	39.633 mi
Registration #13	2016-06-24	39.633 mi
Registration #14	2016-06-24	39.633 mi
Registration #15	2016-06-24	39.633 mi
Registration #16	2016-06-24	39.633 mi
Registration #17	2016-06-24	39.633 mi
Registration #18	2016-06-24	39.633 mi
Registration #19	2016-06-24	39.633 mi
Registration #20	2016-06-24	39.633 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1715 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	07020117059G