





report date: 2024-03-29

General information

| Male | DMM |
|---------------------|-------------------|
| Make | BMW |
| Model | 640 640D M SPORT |
| Colour | Silver |
| Year of manufacture | 2012 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.3 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 308 BHP | |
|-------------------------|---------------------|--|
| Max. torque | 630 Nm at 1.500 rpm | |
| Engine capacity | 2.993 cc | |
| Cylinders | 6 | |
| Fuel type | Diesel | |
| Consumption city | 42.2 mpg | |
| Consumption extra urban | 58.9 mpg | |
| Consumption combined | 51.4 mpg | |
| CO2 emission | 145 g/km | |
| CO2 label | F | |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1


Date 2021-06-14

Pictures 24

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

| MOT expiry date | 2025-03-15 |
|--------------------|------------|
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 12 |
| Total items failed | 3 |

| MOT #10 | | 2024-03-16 11:46 |
|-----------|---|------------------|
| MOT test | number | 301304033689 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-15 |
| Advice | Offside Front Inner Play in steering rack inner joint(s) | |
| Advice | Nearside Front Inner Play in steering rack inner joint(s) | |

| MOT #9 | 2024-03-09 09:58 | |
|--|------------------|--|
| MOT test number | 751406852938 | |
| Result | X Failed | |
| Fail Offside Rear Inner Tyre has ply or cords exposed not safe for road use (5.2.3 (d |) (ii)) | |
| Advice Nearside Front Inner Play in steering rack inner joint(s) | | |
| Fail Brake performance unable to be tested due to wires cords hanging out of both rear tyres (1.2.1 (g)) | | |
| Fail Nearside Rear Inner Tyre has ply or cords exposed not safe for road use (5.2.3 (| (d) (ii)) | |
| Advice Offside Front Inner Play in steering rack inner joint(s) | | |

CarCheck.co.uk page 3/12



MOT #8

RO62XLU report date: 2024-03-29

2023-03-10 17:26

MOT test number 349836127926

Result
✓ Passed

Advice Nearside Rear Outer Brake pad(s) wearing thin outer brake pad (1.1.13 (a) (ii))

Advice Nearside Front Play in steering rack inner joint(s)

MOT #7 2022-03-12 11:30

MOT test number 923310988212

Result \sqrt{Passed}

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Tyre worn close to legal limit/worn on edge Both Sides - 275/30 R20 97Y (5.2.3 (e))

MOT #6 2021-02-20 10:39

MOT test number 466115909663

Result \(\sqrt{Passed} \)

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #5 2020-02-15 10:47

MOT test number 150692728291

Result \(\sqrt{Passed} \)

MOT #4 2019-03-01 13:53

MOT test number 776877712312

CarCheck.co.uk page 4/12



report date: 2024-03-29

| MOT #3 | 2018-06-14 09:40 |
|-----------------|------------------|
| MOT test number | 874333871543 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2017-07-04 10:12 |
| MOT test number | 755374608614 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2016-07-01 10:22 |
| MOT test number | 757476828246 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 93 |
| MOT expiry date | 15 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



obser of plates

laries scinces

Plate since

RO62XLU

report date: 2024-03-29

| Owner history | |
|--|------|
| For how long did the current and previous owner(s) have this BMW? How many owners did this BMW h Check it in the premium report and see all owner registrations. Download the full report here . | ave? |
| ******** | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| ************************************** | |
| More info | > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| | |

OK SING

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2012-11-01 |
| Last registration | 2024-03-16 |
| Complete history | See info |



| Registration #1 | 2012-11-01 | 29 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-07-01 | 30.719 mi |
| Registration #3 | 2017-07-04 | 44.310 mi |
| Registration #4 | 2018-06-14 | 53.840 mi |
| Registration #5 | 2019-03-01 | 64.390 mi |
| Registration #6 | 2020-02-15 | 78.834 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 0.777-46 |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 83% |
| Pedestrian | 78% |
| Safety systems | 100% |
| Overall rating | 90% |
| Video | see crash video |



Dimensions & weight

| Width | 1894 mm |
|---------------------|---------|
| Height | 1369 mm |
| Length | 4894 mm |
| Wheel base | 2855 mm |
| Kerb weight | 1715 kg |
| Max. allowed weight | 2220 kg |

Additional information

| Fuel tank capacity | 70 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 2 | |
| Number of seats CarCheck.co.uk | 4 | page 12/12 |

Number of axles 2
Engine number 35237989