



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Silver
Year of manufacture	2010
Top speed	117 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 5

Date	2021-08-28
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 4

Date	2021-08-06
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 3

Date	2021-07-14
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-06-16
------	------------

Pictures

9

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date

2021-05-22

Pictures

9

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-09
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	28
Total items failed	6

MOT #15 2023-09-10 16:24

MOT test number 292679287664

Result ✓ Passed

Next expiry date 2024-09-09

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14 2023-09-10 16:24

MOT test number 507602955427

Result ✗ Failed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement Both front (5.3.4 (a) (i))

**MOT #13** 2022-09-08 13:39**MOT test number** 421017234857**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))**MOT #12** 2022-09-07 14:01**MOT test number** 128644233290**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #11** 2021-08-27 09:37**MOT test number** 170349851750**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2020-07-29 08:37**MOT test number** 391899776195**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2020-07-28 08:49**MOT test number** 562562403717**Result** ✗ Failed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #8** 2019-08-20 13:55**MOT test number** 255043632624**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #7** 2018-08-21 10:13**MOT test number** 986704132749**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2017-08-09 09:14**MOT test number** 179223741527**Result** ✓ Passed

Advice Undercarriage trays / splash guards / heat shields / engine covers / component covers obscuring some prescribed areas and or items

Advice Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Offside Front tyre NEARLY WORN DOWN TO CORDS outside prescribed measured area

Advice Handbrake lever is tight / stiff in operation. Function not impaired at time of inspection

Advice Front brake disc worn, pitted or scored, but not seriously weakened both ns and os (3.5.1i)

Advice Nearside Front tyre WORN SMOOTH outside prescribed measured area

MOT #5 2016-08-24 07:34**MOT test number** 991067265502**Result** ✓ Passed**MOT #4** 2015-10-16 10:24**MOT test number** 330299924146**Result** ✓ Passed

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #3 2014-10-24 12:39**MOT test number** 378967894474**Result** ✓ Passed**MOT #2** 2013-10-28 15:37**MOT test number** 396531603389**Result** ✓ Passed



MOT #1	2013-04-17 13:03
MOT test number	939017803149
Result	✓ Passed
<div><div>Notice</div>Both front tyres tread worn very low on edges</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	DE10KAU
Plate since	2019-03-28
Current registration	DE10KAU
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-04-22
Last registration	2023-09-10
Complete history	See info



Registration #1	2010-04-22	21 mi
Registration #2	2013-04-17	16.100 mi
Registration #3	2013-10-28	18.771 mi
Registration #4	2014-10-24	36.044 mi
Registration #5	2015-10-16	56.907 mi
Registration #6	2016-08-24	72.496 mi
Registration #7	2017-08-09	87.157 mi
Registration #8	2018-08-21	99.725 mi
Registration #9	2019-08-20	111.204 mi
Registration #10	2020-07-28	119.078 mi
Registration #11	2020-07-29	119.078 mi
Registration #12	2020-08-20	120.000 mi
Registration #13	2020-09-20	120.000 mi
Registration #14	2020-10-20	120.000 mi
Registration #15	2020-11-20	120.000 mi
Registration #16	2020-12-20	120.000 mi
Registration #17	2021-01-20	120.000 mi
Registration #18	2021-02-20	120.000 mi
Registration #19	2021-03-20	120.000 mi
Registration #20	2021-04-20	120.000 mi
Registration #21	2023-09-10	120.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAY 245436