





report date: 2024-03-28

General information

Make	BMW
Model	530 530D
Colour	Silver
Year of manufacture	2002
Top speed	143 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	410 Nm at 1.750 rpm
Engine capacity	2.926 cc
Cylinders	6
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	221 g/km
CO2 label	K



CarCheck.co.uk page 1/15



GX02MHM report date: 2024-03-28

MOT history

MOT expiry date	2021-08-04
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	55
Total items failed	8

MOT #19	2020-08-05 08:58
MOT test number	497524121911
Result	✓ Passed
Next expiry date	2021-08-04
Advice Brake pipe corroded, covered in grease	or other material (1.1.11 (c))
Minor Windscreen damaged but not adversely	affecting driver's view (3.2 (a) (i))
Advice Rear Brake hose slightly deteriorated (2	1.1.12 (b) (ii))
Advice Front Anti-roll bar linkage ball joint has	slight play Both (5.3.4 (a) (i))
Advice Offside Rear Lens damaged	
Advice Fuel Pipe/s corroded	
Advice Offside Rear Anti-roll bar linkage ball jo	int has slight play (5.3.4 (a) (i))
Advice Front Inner Brake disc worn, but not ex	cessively (1.1.14 (a) (i))
Advice Nearside Front Tyre worn close to legal	limit/worn on edge (5.2.3 (e))
Advice Front Headlamp has a product on the le	ens but not seriously reducing light output (4.1.4 (b))

CarCheck.co.uk page 2/15



Advice

Advice

GX02MHM

report date: 2024-03-28

MOT #18 2020-08-05 08:58

MOT test number 116199677977

Result **X** Failed **Advice** Fuel Pipe/s corroded Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Front Anti-roll bar linkage ball joint has slight play Both (5.3.4 (a) (i)) Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Advice Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Offside Rear Lens damaged

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #17 2019-08-05 15:43

MOT test number 874867222053

Result ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Rear Fuel Pipe/s corroded

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16 2019-08-05 14:37

MOT test number 764137762120

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification Electronic stability control warning lamp indicates a fault (7.12 (e))

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Fuel Pipe/s corroded

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #15

MOT test number

S50969951809

Result

Advice Oil leak

Advice Ubcc

Advice Brake pipe slightly corroded (3.6.B.2c)

MOT #14 2016-05-23 10:40

MOT test number 489720891567

Result ✓ Passed

MOT #13 2015-06-15 14:46 **MOT** test number 526456365165 Result ✓ Passed **Advice** Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Front Anti-roll bar damaged but not seriously weakened (2.4.G.1) Advice Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) **Advice** Offside Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #12 2015-06-15 14:46 **MOT** test number 785566665167 Result × Failed **Advice** Offside Brake pipe slightly corroded (3.6.B.2c) Advice Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Front Anti-roll bar damaged but not seriously weakened (2.4.G.1) Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #11

MOT test number

698607544120

Result

Notice Under-trays fitted obscuring some underside components

 MOT #10
 2013-05-30 17:58

 MOT test number
 735370353185

 Result
 ✓ Passed

 MOT #9
 2012-06-06 15:25

 MOT test number
 525708852158

 Result
 ✓ Passed

 Advice
 Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 6/15



Notice

Advice

GX02MHM

report date: 2024-03-28

MOT #8		2011-06-28 13:34
MOT test	number	757349671162
Result		✓ Passed
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #7	2010-06-29 13:08
MOT test number	213520980451
Result	✓ Passed
MOT #6	2009-06-30 17:27
MOT test number	633661889172
Result	✓ Passed
MOT #5	2008-06-23 13:13
MOT test number	314415478195
Result	✓ Passed
MOT #4	2007-06-27 11:39
MOT test number	733458177159
Result	✓ Passed
Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	

MOT #3	2006-06-21 15:13
MOT test number	330002476146
Result	✓ Passed

Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Rear number plate slightly deteriorated noted.

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #2

MOT test number

Result

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #1

MOT test number

893098675151

Result

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax expired: 28 November 2020



Expired: 4 August 2021

Tax status	Expired at 28 November 2020
Days left	1249 days too late
MOT expiry date	4 August 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

o mile motory	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NE CITY OF THE CIT
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2002-07-01
Last registration	2020-08-05
Complete history	See info



Registration #1	2002-07-01	9 mi
Registration #2	2005-06-27	38.471 mi
Registration #3	2006-06-21	51.211 mi
Registration #4	2007-06-27	63.414 mi
Registration #5	2008-06-23	75.719 mi
Registration #6	2009-06-30	90.227 mi
Registration #7	2010-06-29	100.986 mi
Registration #8	2011-06-28	113.987 mi
Registration #9	2012-06-06	129.912 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.177 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1435 mm
Length	4775 mm
Kerb weight	1700 kg
Max. allowed weight	2165 kg

Additional information

Fuel tank capacity	70
Number of doors	4
Number of axles	2
Engine number	31765083

CarCheck.co.uk page 15/15