



report date: 2024-03-28

General information

|                     |                                      |
|---------------------|--------------------------------------|
| Make                | VOLKSWAGEN                           |
| Model               | TRANSPORTER T28 TDI P/V HIGHLINE BMT |
| Colour              | Blue                                 |
| Year of manufacture | 2018                                 |
| Top speed           | 94 mph                               |
| 0 - 100 km/h        | 11.6 seconds                         |
| 0 - 60 mph          | 15.4 seconds                         |
| Gearbox             | 5 speed Manual                       |

Engine & fuel consumption

|                         |                           |
|-------------------------|---------------------------|
| Power                   | 110 kW / 150 HP / 101 BHP |
| Max. torque             | 340 Nm at 1.500 rpm       |
| Engine capacity         | 1.968 cc                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 40.4 mpg                  |
| Consumption extra urban | 54.3 mpg                  |
| Consumption combined    | 47.9 mpg                  |
| CO2 emission            | 156 g/km                  |
| CO2 label               | G                         |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-31 |
| MOT pass rate      | 83 %       |
| MOT passed         | 5          |
| Failed MOT tests   | 1          |
| Total advice items | 7          |
| Total items failed | 1          |

|                  |   |
|------------------|---|
| MOT #6           | 2023-10-16 14:08  |
| MOT test number  | 404824307453  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-10-31  |
| <b>Advice</b>    | Offside Front Inner Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e))  |
| <b>Minor</b>     | Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |
| <b>Advice</b>    | Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))  |

|                                |   |
|--------------------------------|---|
| MOT #5                         | 2023-10-16 14:08  |
| MOT test number                | 295118666949  |
| Result                         | ✗ Failed  |
| <b>Advice</b>                  | Offside Front Inner Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e))  |
| <b>Pass with rectification</b> | Nearside Stop lamp(s) not working (4.3.1 (a) (ii))  |
| <b>Advice</b>                  | Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))  |
| <b>Minor</b>                   | Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) |

|                 |                  |
|-----------------|------------------|
| MOT #4          | 2022-11-01 17:08 |
| MOT test number | 365446225261     |
| Result          | ✓ Passed         |



|                 |                         |
|-----------------|-------------------------|
| MOT #3          | 2022-04-25 14:33        |
| MOT test number | 637550883238            |
| Result          | ✓ Passed                |
| Advice          | Engine undertray fitted |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2021-05-04 11:53 |
| MOT test number | 299330002925     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2020-08-27 07:34 |
| MOT test number | 386109466744     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
31 October 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 November          |
| <b>Days left</b>        | 186                             |
| <b>MOT expiry date</b>  | 31 October 2024                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|                                  |            |
|----------------------------------|------------|
| <b>Vehicle class</b>             | 39         |
| <b>Standard rate (12 months)</b> | £ 320,00,- |
| <b>Standard rate (6 months)</b>  | £ 176,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>GF18WLZ</b> |
| Plate since          | 2019-06-29   |
| Current registration |  <b>GF18WLZ</b> |
| Plate since          | 2019-06-29   |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >





Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 7                        |
| First mileage registration | 2018-05-04               |
| Last registration          | 2023-10-16               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2018-05-04 | 14 mi     |
| Registration #2 | 2020-08-27 | 31.375 mi |
| Registration #3 | 2021-05-04 | 35.495 mi |
| Registration #4 | 2022-04-25 | 39.103 mi |
| Registration #5 | 2023-05-20 | 39.377 mi |
| Registration #6 | 2023-05-20 | 39.377 mi |
| Registration #7 | 2023-05-20 | 39.377 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 79%                             |
| Children       | 74%                             |
| Pedestrian     | 32%                             |
| Safety systems | 57%                             |
| Overall rating | 66%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2397 mm |
| Height              | 1990 mm |
| Length              | 5304 mm |
| Wheel base          | 3400 mm |
| Kerb weight         | 1942 kg |
| Max. allowed weight | 2800 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |

|                 |            |
|-----------------|------------|
| Number of seats | 3          |
| Number of axles | 2          |
| Engine number   | CXGB122204 |