



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D SE
Colour	Gold
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-01
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #17	2023-08-24 14:22
MOT test number	820951303494
Result	✓ Passed
Next expiry date	2024-08-30

MOT #16	2022-08-26 15:33
MOT test number	978342442715
Result	✓ Passed

MOT #15	2021-08-31 09:47
MOT test number	648838879652
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #14	2021-08-24 11:59
MOT test number	295562781083
Result	✓ Passed

**MOT #13** 2020-09-16 13:59**MOT test number** 343986481954**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))**MOT #12** 2019-05-20 14:25**MOT test number** 650005093721**Result** ✓ Passed**MOT #11** 2018-06-04 14:15**MOT test number** 405187111242**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-06-04 11:23**MOT test number** 311071729283**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2017-06-14 08:43**MOT test number** 457409582701**Result** ✓ Passed**MOT #8** 2017-03-02 10:47**MOT test number** 540796049651**Result** ✓ Passed

**MOT #7** 2016-02-25 12:37**MOT test number** 545837225980**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-03-12 10:33**MOT test number** 608551275069**Result** ✓ Passed**MOT #5** 2015-03-12 10:33**MOT test number** 239931875065**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2014-03-24 16:45**MOT test number** 335543684034**Result** ✓ Passed**MOT #3** 2013-02-07 10:07**MOT test number** 798338433086**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2012-02-22 10:41
MOT test number	148753052072
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-01-13 16:27
MOT test number	778013611055
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-31
Last registration	2023-08-24
Complete history	See info



Registration #1	2008-01-31	14 mi
Registration #2	2011-01-13	18.810 mi
Registration #3	2012-02-22	33.861 mi
Registration #4	2013-02-07	49.104 mi
Registration #5	2014-03-24	63.754 mi
Registration #6	2015-03-12	67.374 mi
Registration #7	2016-02-25	70.427 mi
Registration #8	2017-03-02	72.370 mi
Registration #9	2017-06-14	72.626 mi
Registration #10	2018-06-20	75.377 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2020-06-20	75.377 mi
Registration #13	2021-06-20	75.377 mi
Registration #14	2022-06-20	75.377 mi
Registration #15	2023-06-20	75.377 mi
Registration #16	2024-06-20	75.377 mi
Registration #17	2025-06-20	75.377 mi
Registration #18	2026-06-20	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1490 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1670 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	585359