



 **YR67VLN**


report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY
Colour	White
Year of manufacture	2017
Gearbox	-

Engine & fuel consumption

Engine capacity	2.198 cc
Fuel type	Diesel
CO2 emission	229 g/km
CO2 label	L







Internet history

Entry 1

Date	2022-06-12
Pictures	16
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-06-10
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #6	2023-06-02 14:45
MOT test number	298476686592
Result	✓ Passed
Next expiry date	2024-06-10
Advice	Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #5	2022-06-11 08:44
MOT test number	220381613338
Result	✓ Passed

MOT #4	2021-09-28 15:20
MOT test number	196303391447
Result	✓ Passed
Minor	Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #3** 2021-09-28 15:20**MOT test number** 835282112718**Result** ✗ Failed**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #2** 2020-09-29 08:05**MOT test number** 231649400465**Result** ✓ Passed**MOT #1** 2020-09-25 09:03**MOT test number** 767663637614**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear amber side marker lamp inoperative**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
First licence fee (12 months)	£ 2.220,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 2.605,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YR67VLN
Plate since	2019-09-29
Current registration	YR67VLN
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-29
Last registration	2023-06-02
Complete history	See info



Registration #1	2017-09-29	10 mi
Registration #2	2020-09-25	57.060 mi
Registration #3	2020-09-29	57.060 mi
Registration #4	2021-09-28	74.522 mi
Registration #5	2022-06-02	75.277 mi
Registration #6	2022-06-02	75.277 mi
Registration #7	2022-06-02	75.277 mi
Registration #8	2023-06-02	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Number of seats	3
Engine number	TRJA0949658