



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SE SPORT
Colour	Grey
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-29
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-21
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	43
Total items failed	12

MOT #18	2023-05-22 14:00
---------	------------------

MOT test number	965180213124
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-21
------------------	------------

- Advice** Steering rack has slight leak of fluid
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Exhaust mounting defective Hangers are broken at flexi joint (6.1.2 (a))
- Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt Slightly insecure and moving about (2.1.3 (g) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases Flexi joint is damaged and leaking (6.1.2 (a))

**MOT #17**

2023-05-19 12:41

MOT test number

235307559546

Result**✗ Failed**

Minor Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt
Slightly insecure and moving about (2.1.3 (g) (i))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))

Advice Exhaust mounting defective Hangers are broken at flexi joint (6.1.2 (a))

Advice Steering rack has slight leak of fluid

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Exhaust has a minor leak of exhaust gases Flexi joint is damaged and leaking (6.1.2 (a))

MOT #16

2022-04-23 10:29

MOT test number

636640393310

Result**✓ Passed****MOT #15**

2021-04-22 08:49

MOT test number

503997298804

Result**✓ Passed**

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside headlamp lens misted

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #14**

2020-05-01 07:56

MOT test number

634381911785

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13**

2020-03-24 14:31

MOT test number

558074784321

Result

✗ Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Upper Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Headlamp aim too high (4.1.2 (a))**Advice** Nearside front side marker lamp not working**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #12** 2019-03-26 15:25**MOT test number** 877021255562**Result** ✓ Passed**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2019-03-26 15:25**MOT test number** 113703081046**Result** ✗ Failed**Pass with rectification** Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2018-02-14 16:33**MOT test number** 239560711853**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-02-16 10:40**MOT test number** 987382209794**Result** ✓ Passed**Advice** REAR BRAKE PADS RECHECK 3000 MILES

**MOT #8** 2016-02-24 08:57**MOT test number** 148934476552**Result** ✓ Passed**MOT #7** 2016-02-24 08:57**MOT test number** 536012136360**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2015-03-14 14:24**MOT test number** 689693675021**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Rear suspension rubber bushes deteriorated**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2015-03-14 12:35**MOT test number** 986303575024**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Front brakes release unevenly (3.7.B.4)**Notice** Rear suspension rubber bushes deteriorated**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2014-02-28 11:05**MOT test number** 579649954068**Result** ✓ Passed



MOT #3	2013-03-04 11:11
MOT test number	798773463077
Result	✓ Passed

MOT #2	2012-03-01 10:36
MOT test number	176371362008
Result	✓ Passed

MOT #1	2011-02-24 08:30
MOT test number	689105451098
Result	✓ Passed

Notice

Oil leak

Advice

Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
21 May 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	21 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-03
Last registration	2023-05-22
Complete history	See info



Registration #1	2008-03-03	19 mi
Registration #2	2011-02-24	50.711 mi
Registration #3	2012-03-01	59.977 mi
Registration #4	2013-03-04	65.674 mi
Registration #5	2014-02-28	72.915 mi
Registration #6	2015-03-14	85.749 mi
Registration #7	2015-03-14	85.749 mi
Registration #8	2016-02-24	89.207 mi
Registration #9	2016-02-24	89.207 mi
Registration #10	2017-02-16	93.280 mi
Registration #11	2018-05-22	95.277 mi
Registration #12	2018-05-22	95.277 mi
Registration #13	2018-05-22	95.277 mi
Registration #14	2018-05-22	95.277 mi
Registration #15	2018-05-22	95.277 mi
Registration #16	2018-05-22	95.277 mi
Registration #17	2018-05-22	95.277 mi
Registration #18	2018-05-22	95.277 mi
Registration #19	2018-05-22	95.277 mi
Registration #20	2018-05-22	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1328 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	150885