



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP DUALOGIC
Colour	Black
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	113 g/km
CO2 label	C





MOT history

MOT expiry date	2025-02-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	35
Total items failed	3

MOT #13	2024-01-10 11:41
MOT test number	158085466898
Result	✓ Passed
Next expiry date	2025-02-09

MOT #12	2023-01-24 12:46
MOT test number	831579235430
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge starting to wear outer edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2023-01-19 13:43
MOT test number	372525468419
Result	✗ Failed
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Front Macpherson strut pin or bush excessively worn top mount (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge starting to wear outer edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10**

2022-02-03 10:42

MOT test number

690966097606

Result

✓ Passed

Advice

Nearside Front Inner Track rod end ball joint has slight play inner joint slight play (2.1.3 (b) (i))

Minor

Offside Front Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))

MOT #9

2021-02-10 13:35

MOT test number

941631713816

Result

✓ Passed

MOT #8

2020-03-23 10:24

MOT test number

927557272114

Result

✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #7** 2020-03-23 10:24**MOT test number** 108906258733**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2019-03-23 09:51**MOT test number** 704626067310**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly damaged o/s door mirror cover slightly damaged (3.3 (b) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear exhaust rearbox corroded (outer skin but not leaking fumes)**MOT #5** 2018-03-17 13:54**MOT test number** 185894735482**Result** ✓ Passed**Advice** Nearside rear tyre worn edges**Advice** Rear exhaust corroded

**MOT #4** 2017-03-25 11:52**MOT test number** 843033441341**Result** ✓ Passed

- Advice** Exhaust system is corroded
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit Also worn on the inner edge (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2016-03-29 10:25**MOT test number** 200012921731**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust rear silencer corroded

MOT #2 2015-03-21 09:55**MOT test number** 108010985466**Result** ✓ Passed

- Notice** Front wipers smeary
- Notice** Rear exhaust clamp has corroded away
- Notice** Nearside rear tyre perishing
- Notice** Rear exhaust outer skin corroded

MOT #1 2014-03-15 13:39**MOT test number** 239414174070**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-04-01
Last registration	2024-01-10
Complete history	See info



Registration #1	2011-04-01	11 mi
Registration #2	2014-03-15	51.335 mi
Registration #3	2015-03-21	67.241 mi
Registration #4	2016-03-29	80.224 mi
Registration #5	2017-03-25	93.761 mi
Registration #6	2018-03-17	106.328 mi
Registration #7	2019-03-23	118.177 mi
Registration #8	2020-03-29	129.926 mi
Registration #9	2021-03-25	141.675 mi
Registration #10	2022-03-21	153.424 mi
Registration #11	2023-03-17	165.173 mi
Registration #12	2024-01-10	176.922 mi
Registration #13		188.671 mi
Registration #14		200.420 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6491843