





report date: 2024-03-29

General information

Make	BMW
Model	316 520D SE
Colour	Blue
Year of manufacture	2016
Top speed	145 mph
0 - 60 mph	7.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/10



Internet history

Entry 4

Date 2023-03-27

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 3

Date 2023-03-23

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 2

Date 2022-02-12

Pictures 26

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2022-02-08

Pictures 26

Listing price <u>View report</u>

CarCheck.co.uk page 2/10













MOT history

MOT expiry date	2024-02-12
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #5		2023-02-13 08:59
MOT test	number	257607542053
Result		✓ Passed
Next expi	ry date	2024-02-12
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge only just passing	(5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Rear diff slight oil leak	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge only just passing (5.2.3 (e))

MOT #4		2022-02-08 10:52
MOT test	number	199625331920
Result		✓ Passed
Advice	Offside Front tyre wearing on outer edge of tyre	
Advice	Nearside Front tyre wearing on outer edge of tyre	

MOT #3	2021-06-04 08:15
MOT test number	492090076869
Result	✓ Passed
Advice Rear Oil leak, but not excessive axle (8.4.1 (a) (i))	

CarCheck.co.uk page 3/10



 MOT #2
 2020-06-30 13:00

 MOT test number
 364877639111

 Result
 ✓ Passed

MOT #1 2019-04-12 12:37 **MOT** test number 902966742452 Result ✓ Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside rear light lens cracked/damaged but not affecting light output Advice Tyre worn close to legal limit/worn on edge both rears 2mm (5.2.3 (e)) **Advice** Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-26
Last registration	2023-02-13
Complete history	See info



Registration #1	2016-05-26	27 mi
Registration #2	2019-04-12	50.918 mi
Registration #3	2020-06-30	60.992 mi
Registration #4	2021-06-04	67.634 mi
Registration #5		71.777 66
Registration #6		77,777 46
Registration #7		11.777 es
Registration #8		77,777 44
Registration #9		71.777 66
Registration #10		11.777 es

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
50295	
50482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1475 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1630 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pag	ge 10/10

Number of axles 2

Engine number 73209539