





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA MYLIFE
Colour	White
Year of manufacture	2011
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2


Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2021-01-21

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-06
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	20
Total items failed	0

MOT #11		2023-08-07 15:59
MOT test	number	410488721302
Result		✓ Passed
Next expi	ry date	2024-08-06
Advice	Rear Coil spring corroded N/S and O/S (5.3.1 (b) (i))	
Advice	Exhaust rear silencer heavily corroded - Outer skin breaking apart	
Advice	Front Direction indicator slightly discoloured N/S and O/S (4.4.3 (a))	
Advice	Rear Lower Shock absorbers has a slightly worn bush N/S and O/S (5.3.2 (c))	

MOT #10	202	23-08-03 12:13
MOT test	number	560133825456
Result		🗙 Failed
MAJOR (i))	Front Lower Suspension arm pin or bush excessively worn N/S and O/S split from cas	ings (5.3.4 (a)
Advice	Rear Lower Shock absorbers has a slightly worn bush N/S and O/S (5.3.2 (c))	
Advice	Front Direction indicator slightly discoloured N/S and O/S (4.4.3 (a))	
Advice	Rear Coil spring corroded N/S and O/S (5.3.1 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm - Badly cracked in tre-	ad (5.2.3 (e))
Advice	Exhaust rear silencer heavily corroded - Outer skin breaking apart	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

127066166135

Result

Advice Rear Upper Shock absorbers has a slightly worn bush N/S and O/S (5.3.2 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm - Cracking in tread (5.2.3 (e))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement N/S and O/S (5.3.4 (a) (i))

Advice Rear Direction indicator slightly discoloured N/S and O/S (4.4.3 (a))

MOT #8

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7

MOT test number

Result

Advice

Nearside Rear Exhaust silencer slightly loose outer skin rustted (8.1.1 (b) (i))

MOT #6

MOT test number

Result

2019-10-02 14:39

340800491656

✓ Passed

MOT #5

MOT test number

824664140524

Result

Advice Both the front and the nearside rear tyres are all badly perished

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4	2017-07-25 10:07
MOT test number	276385860452
Result	✓ Passed
Advice Both the front and the nearside rear tyres are all becoming perished	

MOT #3	2016-07-08 11:04
MOT test number	592806783789
Result	✓ Passed
Advice Both the rear tyres are becoming perished	

MOT #2	2015-07-16 10:43
MOT test number	209907295122
Result	✓ Passed
MOT #1	2014-07-21 09:54
MOT test number	367942304260
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	6 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	استحاجاتا
Owner	nistory
OVVIICI	IIIJCOI y

*		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	OK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



OE11NZM report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-07-22
Last registration	2023-08-07
Complete history	See info



Registration #1	2011-07-22	18 mi
Registration #2	2014-07-21	7.442 mi
Registration #3	2015-07-16	9.676 mi
Registration #4	2016-07-08	11.817 mi
Registration #5	2017-07-25	13.212 mi
Registration #6	2018-07-20	13.630 mi
Registration #7	2019-10-02	15.888 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number6544135