





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	Black
Year of manufacture	2012
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



SL12NGG report date: 2024-03-29

MOT history

MOT expiry date	2025-03-06
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	26
Total items failed	5

MOT #14		2024-02-19 14:49
MOT test	number	999973532190
Result		✓ Passed
Next expi	ry date	2025-03-06
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Exhaust is corroded	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2024-02-19 08:53 624723074863 **MOT** test number Result × Failed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Exhaust is corroded Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail **Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #12

MOT test number

Fesult

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Exhaust is corroded

Advice

Coil spring corroded All 4 corners. (5.3.1 (b) (i))

MOT #11		2022-02-16 08:47
MOT test	number	103387452111
Result		✓ Passed
Advice	Coil spring corroded All 4 springs are heavily corroded. (5.3.1 (b) (i))	
Advice	Exhaust system is corroded.	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10

MOT test number

247002305526

Result

Advice Under trays fitted obscuring full inspection

MOT #9

MOT test number

Result

Advice

Oil leak, but not excessive sump corroded plus has a seepage (8.4.1 (a) (i))

Advice

Exhaust system corroded

MOT test number

258004106040

Result

Advice Exhaust system corroded

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear wishbone bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive sump corroded plus has a seepage (8.4.1 (a) (i))

MOT #7

MOT test number

Result

2020-03-23 16:49

666151754111

√ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #6	2020-03-23 15:34
MOT test number	677039829045
Result	× Failed
Fail Offside Headlamp aim too high (4.1.2 (a))	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2019-03-22 12:23
MOT test number	135467485924
Result	✓ Passed
MOT #4	2018-03-20 10:45
MOT test number	412428746491
Result	✓ Passed
MOT #3	2017-03-21 13:36
MOT test number	905110088813
Result	✓ Passed
MOT #2	2016-03-22 11:13
MOT test number	823615765315
Result	✓ Passed
MOT #1	2015-03-19 17:30
MOT test number	159958875423
Result	✓ Passed

CarCheck.co.uk page 6/13



SL12NGG report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-20
Last registration	2024-02-19
Complete history	See info



Registration #1	2012-03-20	19 mi
Registration #2	2015-03-19	10.365 mi
Registration #3	2016-03-22	12.458 mi
Registration #4	2017-03-21	15.028 mi
Registration #5	2018-03-20	17.669 mi
Registration #6	2019-03-22	20.318 mi
Registration #7	2020-03-23	22.482 mi
Registration #8	2020-03-23	24.547 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

77,777 86

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 6492127