



RENAULT

HY07PUU

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Gold
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg




LABEL UNKNOWN



Internet history

Entry 3

Date	2023-02-26
Pictures	13
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-10-26
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-10-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #17	2024-01-09 12:43
MOT test number	229099334618
Result	✓ Passed
Next expiry date	2025-01-08
Advice	Offside Play in steering rack inner joint(s)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2024-01-08 12:39
MOT test number	899538159151
Result	✗ Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Front Body component damaged and likely to cause injury headlamp lens (6.2.1 (a) (i))
Advice	Offside Play in steering rack inner joint(s)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

**MOT #15**

2022-12-14 16:42

MOT test number

416570220971

Result

✓ Passed

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**MOT #14**

2022-12-05 09:45

MOT test number

100742416108

Result

✗ Failed

MAJOR Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MAJOR** Rear Direction indicator incorrect colour both sides (4.4.3 (a))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MAJOR** Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**MOT #13**

2021-11-08 15:52

MOT test number

112890184855

Result

✓ Passed

Advice Play in steering rack inner joint(s)**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension component corroded but not seriously weakened hub (5.3.3 (b) (i))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Suspension component corroded but not seriously weakened hub (5.3.3 (b) (i))

**MOT #12**

2020-10-07 09:07

MOT test number

890597906720

Result

✓ Passed

- Advice** Manufacturers engine and body/sill covers fitted restricting inspection of components
- Advice** Front Suspension component corroded but not seriously weakened offside and nearside hubs/strut etc. (5.3.3 (b) (i))
- Advice** Front Lower Suspension arm corroded but not seriously weakened offside and nearside badly corroded (5.3.3 (b) (i))
- Advice** Coil spring corroded all springs (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both inner faces badly corroded (1.1.14 (a) (ii))

MOT #11

2019-09-11 10:21

MOT test number

887664345854

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Various suspension components corroded but not weakened
- Advice** Manufacturers engine and body/sill covers fitted restricting inspection of components

MOT #10

2018-09-10 14:13

MOT test number

181051113018

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Various suspension components badly corroded but not excessively weakened
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-08-31 09:28**MOT test number** 238148820101**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened offside and nearside inner faces (1.1.14 (a) (ii))**Advice** Various suspension components badly corroded but not excessively weakened**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Play in steering rack inner joint(s)**MOT #8** 2017-08-24 13:28**MOT test number** 661408125326**Result** ✓ Passed**Advice** Manufactures engine and body/sill covers fitted restricting inspection of components**MOT #7** 2016-09-09 09:32**MOT test number** 712402411440**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)**Advice** Manufactures engine and body/sill covers fitted restricting inspection of components**MOT #6** 2015-05-18 10:30**MOT test number** 237288035149**Result** ✓ Passed

**MOT #5** 2014-04-15 11:08**MOT test number** 516385904140**Result** ✓ Passed**MOT #4** 2012-10-08 11:09**MOT test number** 375382782203**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-10-08 11:09**MOT test number** 365542382453**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2011-09-08 11:10**MOT test number** 726371251282**Result** ✓ Passed**MOT #1** 2010-09-03 11:59**MOT test number** 474026840236**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-22
Last registration	2024-01-09
Complete history	See info



Registration #1	2007-03-22	24 mi
Registration #2	2010-09-03	27.068 mi
Registration #3	2011-09-08	30.452 mi
Registration #4	2012-10-08	33.175 mi
Registration #5	2014-04-15	37.131 mi
Registration #6	2015-05-18	39.564 mi
Registration #7	2016-09-09	42.736 mi
Registration #8	2017-08-24	44.625 mi
Registration #9	2018-08-31	46.312 mi
Registration #10	2018-09-10	46.322 mi
Registration #11	2019-05-20	50.277 mi
Registration #12	2019-05-20	50.277 mi
Registration #13	2019-05-20	50.277 mi
Registration #14	2019-05-20	50.277 mi
Registration #15	2019-05-20	50.277 mi
Registration #16	2019-05-20	50.277 mi
Registration #17	2019-05-20	50.277 mi
Registration #18	2019-05-20	50.277 mi
Registration #19	2019-05-20	50.277 mi
Registration #20	2019-05-20	50.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm

Additional information

Number of seats	4
Number of axles	2
Engine number	NOT KNOWN