



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	GLE GLE 250 D 4MATIC AMG NIGHT EDI
Colour	Grey
Year of manufacture	2018
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 201 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-03-03
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2022-02-23
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-03-23
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #5	2024-03-01 12:34
MOT test number	205921671528
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Under tray fitted
Advice	Rear Brake disc worn, but not excessively slight lipped (1.1.14 (a) (i))

MOT #4	2023-03-24 16:26
MOT test number	941547215954
Result	✓ Passed

MOT #3	2022-09-26 10:26
MOT test number	445074986447
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))



MOT #2	2022-09-23 15:49
MOT test number	670311445421
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Fail	Nearside Cab steps in such a condition that it is likely to cause injury (6.2.8 (b))
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
MOT #1	2021-08-09 15:05
MOT test number	192967932604
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-05
Last registration	2024-03-01
Complete history	See info



Registration #1	2018-09-05	23 mi
Registration #2	2021-08-09	32.096 mi
Registration #3		
Registration #4	2022-09-23	47.309 mi
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2141 mm
Height	1789 mm
Length	4819 mm
Wheel base	2915 mm
Kerb weight	2065 kg

Additional information

Fuel tank capacity	93 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	65196034652893