



HYUNDAI




report date: 2024-03-28

## General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2022-06-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2022-05-05
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2024-05-03
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #7	2023-04-29 10:22
MOT test number	648628730194
Result	✓ Passed
Next expiry date	2024-05-03
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6	2022-05-04 14:40
MOT test number	475002134107
Result	✓ Passed

MOT #5	2022-05-03 14:25
MOT test number	379790190212
Result	✗ Failed
<b>DANGEROUS</b>	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
<b>DANGEROUS</b>	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>MAJOR</b>	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
<b>DANGEROUS</b>	Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
<b>DANGEROUS</b>	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #4 2021-06-22 08:21

MOT test number 993417712973

Result ✓ Passed

MOT #3 2020-06-18 08:36

MOT test number 530351881080

Result ✓ Passed

**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #2 2019-11-04 10:34

MOT test number 182592868045

Result ✓ Passed

**Advice** Rear tyres perished.

MOT #1 2018-11-30 10:50

MOT test number 255454060906

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
3 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	3 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-11-30
Last registration	2023-04-29
Complete history	<a href="#">See info</a>



Registration #1	2015-11-30	24 mi
Registration #2	2018-11-30	35.376 mi
Registration #3	2019-11-04	45.497 mi
Registration #4	2020-06-18	50.388 mi
Registration #5	2021-06-22	59.269 mi
Registration #6	2022-06-22	68.150 mi
Registration #7	2023-04-29	77.031 mi
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDFZ369714