



report date: 2024-03-28

General information

| | |
|---------------------|---------------------|
| Make | FORD |
| Model | S-MAX TITANIUM TDCI |
| Colour | Black |
| Year of manufacture | 2009 |
| Top speed | 132 mph |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 173 BHP |
| Max. torque | 400 Nm at 2.750 rpm |
| Engine capacity | 2.179 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.4 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 174 g/km |
| CO2 label | H |






Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-07-10 |
| Pictures | 15 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-23 |
| Pictures | 3 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-26 |
| MOT pass rate | 63 % |
| MOT passed | 10 |
| Failed MOT tests | 6 |
| Total advice items | 59 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #16 | 2023-06-27 09:33 |
| MOT test number | 880429853933 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-26 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #15 | 2023-06-27 07:03 |
| MOT test number | 693985239204 |
| Result | ✗ Failed |
| DANGEROUS | Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |
| MAJOR | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|-----------------------------|
| MOT #14 | 2022-06-08 14:32 |
| MOT test number | 104691977323 |
| Result | ✓ Passed |
| Advice | O/S/R LIGHT UNIT IS DAMAGED |

**MOT #13**

2022-06-08 08:46

MOT test number

806457477853

Result**✗ Failed****DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Exhaust system insecure FRONT,CENTRE AND REAR BRACKETS ARE BROKEN (6.1.2 (a))**Advice** O/S/R LIGHT UNIT IS DAMAGED**MOT #12**

2021-01-13 17:05

MOT test number

962056808785

Result**✓ Passed****Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Exhaust mounting defective both broken (6.1.2 (a))**Minor** Offside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #11**

2021-01-11 16:26

MOT test number

249714374661

Result**✗ Failed****Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Exhaust mounting defective both broken (6.1.2 (a))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Minor** Offside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #10** 2019-04-10 15:36**MOT test number** 215278532429**Result** ✓ Passed**Advice** 2 rear exhaust hangers broken**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2019-04-08 11:22**MOT test number** 628495822680**Result** ✗ Failed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**Advice** 2 rear exhaust hangers broken**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #8** 2018-03-13 11:42**MOT test number** 361766733367**Result** ✓ Passed

**MOT #7**

2017-03-20 16:21

MOT test number

124946169475

Result

✓ Passed

- Advice** Nearside Front Upper Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Advice** Offside Front Tyre worn close to the legal limit 1.6mm tread, worn inner shoulder (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened disc also lipped on inner and outer edge (3.5.1i)
- Advice** Exhaust system corroded, and mountings quite thin/weak
- Advice** Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement front bush is split (2.4.G.2)
- Advice** Offside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Tyre worn close to the legal limit 1.6mm tread, worn on inner shoulder tyre size 235/45/18 (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened also lipped inner and outer edge (3.5.1i)
- Advice** Washer bottle cap missing
- Advice** Nearside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement front bush is split (2.4.G.2)
- Advice** Both rear discs, corroded and lipped on inner and outer edge

**MOT #6**

2017-03-20 16:21

MOT test number

345376097033

Result**✗ Failed**

- Advice** Offside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Tyre worn close to the legal limit 1.6mm tread, worn on inner shoulder tyre size 235/45/18 (4.1.E.1)
- Advice** Washer bottle cap missing
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened also lipped inner and outer edge (3.5.1i)
- Advice** Both rear discs, corroded and lipped on inner and outer edge
- Advice** Nearside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement front bush is split (2.4.G.2)
- Advice** Nearside Front Upper Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Pass with rectification** Offside Rear Inner Rear position lamp(s) not working 207 bulb (1.1.A.3b)
- Advice** Offside Front Tyre worn close to the legal limit 1.6mm tread, worn inner shoulder (4.1.E.1)
- Advice** Exhaust system corroded, and mountings quite thin/weak
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened disc also lipped on inner and outer edge (3.5.1i)
- Advice** Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement front bush is split (2.4.G.2)

MOT #5

2016-01-14 14:55

MOT test number

130593779606

Result**✓ Passed**

- Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Advice** Rear seats folded down at time of test
- Advice** Tyre size 235/45/18

**MOT #4** 2016-01-14 11:57**MOT test number** 467776779439**Result** ✗ Failed**Advice** Rear seats folded down at time of test**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Advice** Tyre size 235/45/18**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside front tyre worn inner edge**MOT #3** 2015-01-06 11:07**MOT test number** 398886705051**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Notice** Under-trays fitted obscuring some underside components**Notice** Rear trailing arm bushes splitting**Notice** Rear seats folded down at time of test(not in use/unable to test belts)**MOT #2** 2013-10-12 08:25**MOT test number** 908575983219**Result** ✓ Passed**MOT #1** 2012-10-06 11:03**MOT test number** 669110482207**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
26 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 62 |
| MOT expiry date | 26 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | RA59RFY |
| Plate since | 2019-03-28 |
| Current registration | RA59RFY |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2009-10-16 |
| Last registration | 2023-06-27 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-10-16 | 23 mi |
| Registration #2 | 2012-10-06 | 27.813 mi |
| Registration #3 | 2013-10-12 | 37.350 mi |
| Registration #4 | 2015-01-06 | 56.197 mi |
| Registration #5 | 2016-01-14 | 74.566 mi |
| Registration #6 | 2016-01-14 | 74.566 mi |
| Registration #7 | 2017-03-20 | 87.449 mi |
| Registration #8 | 2017-03-20 | 87.449 mi |
| Registration #9 | 2018-03-13 | 97.684 mi |
| Registration #10 | 2019-04-08 | 110.631 mi |
| Registration #11 | 2019-06-20 | 110.631 mi |
| Registration #12 | 2019-06-20 | 110.631 mi |
| Registration #13 | 2019-06-20 | 110.631 mi |
| Registration #14 | 2019-06-20 | 110.631 mi |
| Registration #15 | 2019-06-20 | 110.631 mi |
| Registration #16 | 2019-06-20 | 110.631 mi |
| Registration #17 | 2019-06-20 | 110.631 mi |
| Registration #18 | 2019-06-20 | 110.631 mi |
| Registration #19 | 2019-06-20 | 110.631 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1884 mm |
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1974 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

Engine number

9B85931