



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	MR2 ROADSTER
Colour	Silver
Year of manufacture	2004
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-12-20
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-15
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	22
Total items failed	18

MOT #25	2024-02-10 14:15
MOT test number	407041508937
Result	✓ Passed
Next expiry date	2025-02-15

MOT #24	2024-02-09 16:23
MOT test number	103079212304
Result	✗ Failed
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #23	2023-02-16 08:27
MOT test number	306936040603
Result	✓ Passed

**MOT #22**

2022-10-24 12:33

**MOT test number**

596086951823

**Result****✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #21**

2021-11-23 10:25

**MOT test number**

697882342214

**Result****✓ Passed****Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #20**

2020-11-18 10:40

**MOT test number**

427555749372

**Result****✓ Passed****MOT #19**

2020-11-10 14:36

**MOT test number**

442685486377

**Result****✗ Failed****Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))

**MOT #18** 2020-11-02 10:22**MOT test number** 186879706824**Result** ✗ Failed**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #17** 2019-05-03 08:12**MOT test number** 959543201077**Result** ✓ Passed**MOT #16** 2018-04-05 10:38**MOT test number** 575055498914**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #15** 2018-04-04 10:08**MOT test number** 503910074304**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #14** 2017-04-10 12:39**MOT test number** 943756418852**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Power steering component(s) has slight seepage from a component (2.3.3b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake binding slightly
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #13** 2016-04-11 10:18**MOT test number** 956459207289**Result** ✓ Passed**MOT #12** 2015-05-12 09:03**MOT test number** 827772435171**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2014-05-09 10:46**MOT test number** 266379724150**Result** ✓ Passed**MOT #10** 2013-05-07 14:32**MOT test number** 218867523453**Result** ✓ Passed

**MOT #9** 2012-05-02 12:30**MOT test number** 727043622117**Result** ✓ Passed**MOT #8** 2011-05-05 12:02**MOT test number** 887295721193**Result** ✓ Passed**MOT #7** 2010-05-06 10:14**MOT test number** 203136920419**Result** ✓ Passed**MOT #6** 2009-05-12 14:52**MOT test number** 993122939164**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Battery insecure**MOT #5** 2008-05-13 12:01**MOT test number** 794724338146**Result** ✓ Passed**Notice** Battery insecure**Notice** N/s/r wheel rim scuffed

**MOT #4** 2008-05-12 12:31**MOT test number** 441273638134**Result** ✗ Failed**Fail** Offside front brake juddering severely (3.7.A.2b)**Notice** N/s/r wheel rim scuffed**Fail** Offside Front brake disc excessively pitted (3.5.1h)**Notice** Battery insecure**MOT #3** 2007-11-20 10:50**MOT test number** 150904627392**Result** ✓ Passed**MOT #2** 2007-11-16 17:58**MOT test number** 890580227371**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2006-11-16 12:17**MOT test number** 560260526332**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
15 February 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	15 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2004-01-09
Last registration	2024-02-10
Complete history	<a href="#">See info</a>



Registration #1	2004-01-09	15 mi
Registration #2	2006-11-16	30.145 mi
Registration #3	2007-11-16	37.833 mi
Registration #4	2007-11-20	37.833 mi
Registration #5	2008-05-12	37.983 mi
Registration #6	2008-05-13	37.987 mi
Registration #7	2009-05-12	41.124 mi
Registration #8	2010-05-06	45.401 mi
Registration #9	2011-05-05	49.541 mi
Registration #10	2012-05-02	54.146 mi
Registration #11	2013-05-07	58.316 mi
Registration #12	2014-05-09	62.563 mi
Registration #13	2015-05-12	66.589 mi
Registration #14	2016-04-11	70.437 mi
Registration #15	2016-05-01	70.437 mi
Registration #16	2016-05-01	70.437 mi
Registration #17	2016-05-01	70.437 mi
Registration #18	2016-05-01	70.437 mi
Registration #19	2016-05-01	70.437 mi
Registration #20	2016-05-01	70.437 mi
Registration #21	2016-05-01	70.437 mi
Registration #22	2016-05-01	70.437 mi
Registration #23	2016-05-01	70.437 mi
Registration #24	2016-05-01	70.437 mi
Registration #25	2016-05-01	70.437 mi
Registration #26	2016-05-01	70.437 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1240 mm
Length	3885 mm
Wheel base	2450 mm
Kerb weight	960 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1ZZ1660206