



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Grey
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-06-27
Pictures	3
Listing price	View report



Video viewing

Book a video viewing with one of our team. See the vehicle from the comfort of your own home.

[Visit our website for more info](#)



Click & Deliver

Complete your deal online or by phone. Then arrange for the sanitised vehicle to be delivered to you.

[Visit our website for more info](#)



Click & Collect

Start your deal online or by phone. When you visit, our safe and clean environment has been designed for a contactless viewing and handover with you.

[Visit our website for more info](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-06-26
Pictures	3
Listing price	View report



Click & Collect

Start your deal online or by phone. When you visit, our safe and clean environment has been designed for a contactless viewing and handover with you.

[Visit our website for more info](#)



Click & Deliver

Complete your deal online or by phone. Then arrange for the sanitised vehicle to be delivered to you.

[Visit our website for more info](#)



Video viewing

Book a video viewing with one of our team. See the vehicle from the comfort of your own home.

[Visit our website for more info](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-06-18
MOT pass rate	100 %
MOT passed	13
Failed MOT tests	0
Total advice items	28
Total items failed	0

MOT #132022-06-16 10:08

MOT test number522216695224

Result✓ Passed

Next expiry date2023-06-18

Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edges (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edges (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #12**

2021-06-19 15:36

MOT test number

534034428832

Result

✓ Passed

- Advice** Under Trays Fitted Obscuring View Of Some Underside Components
- Advice** Rear Anti-roll bar linkage ball joint has slight play N/S & O/S (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin N/S & O/S (1.1.13 (a) (ii))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11

2020-11-19 13:29

MOT test number

844659764663

Result

✓ Passed

MOT #10

2019-10-22 08:04

MOT test number

591352150926

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #9

2018-11-08 09:12

MOT test number

714745666594

Result

✓ Passed

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2017-11-10 14:14**MOT test number** 875804372741**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both front arm rear bushes (2.4.G.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-11-07 14:27**MOT test number** 370370308094**Result** ✓ Passed**MOT #6** 2015-11-12 15:28**MOT test number** 544132897346**Result** ✓ Passed**MOT #5** 2014-11-13 15:57**MOT test number** 189197714395**Result** ✓ Passed**MOT #4** 2013-10-28 16:36**MOT test number** 925621203372**Result** ✓ Passed**MOT #3** 2012-10-03 11:11**MOT test number** 888297872283**Result** ✓ Passed



MOT #2	2012-02-09 15:06
MOT test number	697260242022
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-09-01 13:39
MOT test number	851394040200
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
21 September 2022

✕
MOT

Expired:
18 June 2023

Tax status	Expired at 21 September
Days left	585 days too late
MOT expiry date	18 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YX57YGY
Plate since	2024-03-28
Current registration	 YX57YGY
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-21
Last registration	2022-06-16
Complete history	See info



Registration #1	2007-09-21	21 mi
Registration #2	2010-09-01	50.266 mi
Registration #3	2012-02-09	66.878 mi
Registration #4	2012-10-03	72.597 mi
Registration #5	2013-10-28	82.475 mi
Registration #6	2014-11-13	90.271 mi
Registration #7	2015-11-12	96.976 mi
Registration #8	2016-11-07	103.280 mi
Registration #9	2016-11-07	103.280 mi
Registration #10	2016-11-07	103.280 mi
Registration #11	2016-11-07	103.280 mi
Registration #12	2016-11-07	103.280 mi
Registration #13	2016-11-07	103.280 mi
Registration #14	2016-11-07	103.280 mi
Registration #15	2016-11-07	103.280 mi
Registration #16	2016-11-07	103.280 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN