



report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Silver
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-09
Pictures	23
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-17
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	33
Total items failed	5

MOT #19	2023-09-18 13:27
MOT test number	568107401545
Result	✓ Passed
Next expiry date	2024-09-17
Advice	Direction indicator slightly discoloured Both Rear (4.4.3 (a))
Advice	Headlamp has a product on the lens but not seriously reducing light output Both Front (4.1.4 (b))
Advice	Nearside Rear Nail in tyre

MOT #18	2022-11-29 12:20
MOT test number	795257268551
Result	✓ Passed
Advice	Rear bumper panel damage
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #17** 2021-10-04 11:36**MOT test number** 221094521998**Result** ✓ Passed

- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #16 2021-10-04 08:54**MOT test number** 778613256597**Result** ✗ Failed

- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15 2020-10-03 09:04**MOT test number** 235233779175**Result** ✓ Passed**MOT #14** 2020-10-03 09:04**MOT test number** 570858360927**Result** ✗ Failed

- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #13** 2019-01-24 08:34**MOT test number** 130959173325**Result** ✓ Passed**MOT #12** 2018-01-12 08:48**MOT test number** 765305823434**Result** ✓ Passed**MOT #11** 2017-01-16 14:28**MOT test number** 252222015830**Result** ✓ Passed**MOT #10** 2015-06-05 11:18**MOT test number** 307986055179**Result** ✓ Passed**Notice** Damp around steering rack but no signs of leak**Notice** Rear axle bush's slight play**Notice** Oil leak**Notice** Exhaust corroded**MOT #9** 2014-06-03 09:55**MOT test number** 169544654132**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2013-06-05 11:01**MOT test number** 358506953129**Result** ✓ Passed**Notice** Both front wipers slightly deteriorated**MOT #7** 2013-06-05 11:01**MOT test number** 569396553177**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Notice** Both front wipers slightly deteriorated**MOT #6** 2012-06-01 11:28**MOT test number** 586533052122**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-06-06 10:40**MOT test number** 169767551180**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-06-06 10:40**MOT test number** 537807051194**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Stop lamp not working (1.2.1b)



MOT #3	2010-05-26 17:45
MOT test number	614066440171
Result	✓ Passed

MOT #2	2010-05-25 17:03
MOT test number	613345240125
Result	✗ Failed
<div><div>Fail</div>Offside Front Shock absorber has a serious fluid leak (2.7.3)</div> <div><div>Notice</div>Child seat fitted not allowing full inspection of adult belt</div> <div><div>Fail</div>Offside Stop lamp not working (1.2.1b)</div>	

MOT #1	2009-05-26 14:50
MOT test number	681996049169
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
17 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	GL06LWJ
Plate since	2019-09-28
Current registration	GL06LWJ
Plate since	2019-09-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-06-30
Last registration	2023-09-18
Complete history	See info



Registration #1	2006-06-30	23 mi
Registration #2	2009-05-26	14.599 mi
Registration #3	2010-05-25	20.455 mi
Registration #4	2010-05-26	20.469 mi
Registration #5	2011-06-06	25.625 mi
Registration #6	2012-06-01	31.856 mi
Registration #7	2013-06-05	39.934 mi
Registration #8	2014-06-03	47.805 mi
Registration #9	2015-06-05	55.800 mi
Registration #10	2017-01-16	64.578 mi
Registration #11	2018-06-01	73.577 mi
Registration #12	2019-06-01	82.577 mi
Registration #13	2020-06-01	91.577 mi
Registration #14	2021-06-01	100.577 mi
Registration #15	2022-06-01	109.577 mi
Registration #16	2023-06-01	118.577 mi
Registration #17	2024-06-01	127.577 mi
Registration #18	2025-06-01	136.577 mi
Registration #19	2026-06-01	145.577 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6S21610