



DA04BYJ

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO LX TDCI
Colour	Silver
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	329 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg





Internet history

Entry 1

Date	2021-06-09
Pictures	30
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #22**

2023-12-09 16:09

MOT test number

755144967790

Result**✗ Failed**

- Fail** Offside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting rear cross member (6.2.2 (d) (i))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Wheel bearing so rough it is likely to overheat or break up (5.1.3 (b) (ii))
- Fail** Nearside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting rear cross member (6.2.2 (d) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** General under body corrosion
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #21

2022-01-08 12:51

MOT test number

303895310534

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Upper Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20**

2022-01-08 10:57

MOT test number

195387134704

Result**✗ Failed****Fail**

Nearside Front Direction indicator not working (4.4.1 (a) (ii))

Advice

Offside Rear Upper Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail

Offside Front Direction indicator not working (4.4.1 (a) (ii))

Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19

2020-11-10 13:00

MOT test number

507514162474

Result**✓ Passed****MOT #18**

2020-11-03 14:53

MOT test number

860083014031

Result**✗ Failed****Fail**

Offside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Fail

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #17

2019-05-13 16:00

MOT test number

997835195330

Result**✓ Passed****Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Central Exhaust mounting defective (6.1.2 (a))

**MOT #16** 2018-05-31 10:59**MOT test number** 958545351889**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**MOT #15** 2018-05-25 08:33**MOT test number** 581969313496**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**MOT #14** 2017-06-02 14:30**MOT test number** 800340078345**Result** ✓ Passed**MOT #13** 2017-05-26 11:08**MOT test number** 461844386732**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #12** 2016-05-06 15:07**MOT test number** 471681974575**Result** ✓ Passed**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)

**MOT #11** 2016-05-06 08:23**MOT test number** 529549891570**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 205/55/16 (4.1.E.1)**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**MOT #10** 2015-05-26 09:15**MOT test number** 218346345471**Result** ✓ Passed**MOT #9** 2014-05-08 15:13**MOT test number** 509418324169**Result** ✓ Passed**MOT #8** 2013-05-10 09:22**MOT test number** 888790433101**Result** ✓ Passed**MOT #7** 2012-05-04 09:18**MOT test number** 889095322123**Result** ✓ Passed**Notice** Front brake discs worn and pitted**Notice** Wipers poor**Notice** Front brake pads low

**MOT #6** 2011-05-19 09:48**MOT test number** 569189431152**Result** ✓ Passed**Notice** Front discs pitted**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2010-06-03 12:00**MOT test number** 874934350142**Result** ✓ Passed**Advice** Front brake disc slightly scored (3.5.1h)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-05-28 09:18**MOT test number** 110288749116**Result** ✓ Passed**Notice** Both rear tyres tread cracked**MOT #3** 2008-06-02 12:45**MOT test number** 191364658184**Result** ✓ Passed**MOT #2** 2008-05-31 11:32**MOT test number** 282222658175**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2007-06-01 13:13
MOT test number	552372457103
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-06-03
Last registration	2023-12-09
Complete history	See info



Registration #1	2004-06-03	7 mi
Registration #2	2007-06-01	15.800 mi
Registration #3	2008-05-31	22.265 mi
Registration #4	2008-06-02	22.265 mi
Registration #5	2009-05-28	27.146 mi
Registration #6	2010-06-03	30.531 mi
Registration #7	2011-05-19	36.211 mi
Registration #8	2012-05-04	40.055 mi
Registration #9	2013-05-10	45.100 mi
Registration #10	2014-05-08	49.167 mi
Registration #11	2015-05-26	53.744 mi
Registration #12	2016-05-06	67.562 mi
Registration #13	2016-05-06	67.562 mi
Registration #14	2016-05-06	67.562 mi
Registration #15	2016-05-06	67.562 mi
Registration #16	2016-05-06	67.562 mi
Registration #17	2016-05-06	67.562 mi
Registration #18	2016-05-06	67.562 mi
Registration #19	2016-05-06	67.562 mi
Registration #20	2016-05-06	67.562 mi
Registration #21	2016-05-06	67.562 mi
Registration #22	2016-05-06	67.562 mi
Registration #23	2016-05-06	67.562 mi
Registration #24	2016-05-06	67.562 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1931 mm
Height	1441 mm
Length	4804 mm
Wheel base	2754 mm
Kerb weight	1565 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	4R36276