



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	White
Year of manufacture	2012
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-05-21
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-11
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	16
Total items failed	13

MOT #17	2023-08-03 09:13
MOT test number	444022661560
Result	✓ Passed
Next expiry date	2024-08-11

MOT #16	2023-07-27 09:10
MOT test number	128252828873
Result	✗ Failed
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #15	2022-08-12 15:38
MOT test number	687660184400
Result	✓ Passed

MOT #14	2022-03-04 17:32
MOT test number	851679624013
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2022-03-03 11:11

**MOT test number**

312279789831

**Result****✗ Failed**

**Fail** Offside Rear Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength Cross beam (5.3.6 (a) (i))

**Advice** Rear Coil spring corroded (5.3.1 (b) (i))

**Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

**Fail** Offside Rear Suspension arm corroded and seriously weakened Cross beam (5.3.3 (b) (i))

**Fail** Emissions not tested Due to coolant leak (8.2.1.2 (d))

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12**

2021-03-08 15:13

**MOT test number**

967093366832

**Result****✓ Passed**

**Advice** Oil leak, but not excessive sump corroded (8.4.1 (a) (i))

**Advice** Rear Suspension arm corroded but not seriously weakened rear axle corroded (5.3.3 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11**

2021-03-08 11:05

**MOT test number**

384390633377

**Result****✗ Failed**

**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Oil leak, but not excessive sump corroded (8.4.1 (a) (i))

**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Rear Suspension arm corroded but not seriously weakened rear axle corroded (5.3.3 (b) (i))

**MOT #10** 2020-03-05 16:05**MOT test number** 278220918425**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2020-03-05 12:32**MOT test number** 570521323167**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #8** 2019-02-27 10:51**MOT test number** 227183132391**Result** ✓ Passed**MOT #7** 2018-02-27 10:21**MOT test number** 664424673523**Result** ✓ Passed**MOT #6** 2018-02-27 10:21**MOT test number** 980470997586**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2017-03-02 10:05**MOT test number** 832983049934**Result** ✓ Passed

**MOT #4** 2016-02-05 13:24**MOT test number** 891031101080**Result** ✓ Passed**MOT #3** 2016-02-05 12:30**MOT test number** 463416008561**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2015-02-14 10:13**MOT test number** 359945145083**Result** ✓ Passed**MOT #1** 2015-02-14 09:13**MOT test number** 719895845044**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
11 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	11 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-01
Last registration	2023-08-03
Complete history	<a href="#">See info</a>



Registration #1	2012-03-01	20 mi
Registration #2	2015-02-14	22.493 mi
Registration #3	2015-02-14	22.493 mi
Registration #4	2016-02-05	31.045 mi
Registration #5	2016-02-05	31.045 mi
Registration #6	2017-03-02	38.880 mi
Registration #7	2018-02-27	45.251 mi
Registration #8	2018-02-27	45.251 mi
Registration #9	2019-02-27	49.762 mi
Registration #10	2020-03-05	54.030 mi
Registration #11	2020-03-05	54.030 mi
Registration #12	2020-03-05	54.030 mi
Registration #13	2020-03-05	54.030 mi
Registration #14	2020-03-05	54.030 mi
Registration #15	2020-03-05	54.030 mi
Registration #16	2020-03-05	54.030 mi
Registration #17	2020-03-05	54.030 mi
Registration #18	2020-03-05	54.030 mi
Registration #19	2020-03-05	54.030 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	6492127