






report date: 2024-03-28

### General information

Make	FORD
Model	TRANSIT CONNECT T230 HR P/V
Colour	Silver
Year of manufacture	2011
Top speed	10 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	1.0 mpg
Consumption extra urban	1.0 mpg
Consumption combined	1.0 mpg



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2020-09-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #8	2019-09-13 14:05
MOT test number	988376001477
Result	✓ Passed
Next expiry date	2020-09-12
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #7		2019-09-13 14:05
MOT test number		240698004263
Result		<b>X</b> Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))		

MOT #6	2018-06-25 15:58
MOT test number	650945953659
Result	✓ Passed

CarCheck.co.uk page 2/10



MOT #5 2017-07-28 14:13

**MOT test number** 755520097176

MOT #4 2016-10-12 10:09

**MOT test number** 836674266550

Result 

Passed

**Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2016-10-12 10:09

**MOT test number** 446094547526

Result X Failed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #2** 2015-10-12 10:26

**MOT test number** 732218321829

CarCheck.co.uk page 3/10



MOT #1

MOT test number

Result

Notice Nearside track rod has slight play in ball joint

2014-10-14 14:56

399597984450

✓ Passed

CarCheck.co.uk page 4/10



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	AIR AIR
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 8/10



## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2011-10-21
Last registration	2019-09-13
Complete history	See info



Registration #1	2011-10-21	14 mi
Registration #2	2014-10-14	83.809 mi
Registration #3	2015-10-12	97.478 mi
Registration #4	2016-10-12	116.464 mi
Registration #5	2016-10-12	116.464 mi
Registration #6		11.777 ea
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



### Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	2044 mm
Height	1980 mm
Length	4525 mm
Kerb weight	1438 kg
Max. allowed weight	2340 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Number of axles	2
Engine number	AG11065

CarCheck.co.uk page 10/10