



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-10-01
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-15
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	5

MOT #16	2023-12-16 08:50
MOT test number	499902931022
Result	✓ Passed
Next expiry date	2024-12-15

MOT #15	2023-12-16 08:31
MOT test number	572153534924
Result	✗ Failed
Fail	Front Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #14	2022-12-15 15:26
MOT test number	992226015932
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Coil spring corroded both rear (5.3.1 (b) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened front (1.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Tyre worn close to legal limit/worn on edge both rear 3mm and cracking (5.2.3 (e))

**MOT #13** 2021-12-06 21:58**MOT test number** 307336817363**Result** ✓ Passed**MOT #12** 2021-02-01 15:23**MOT test number** 199025900836**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2020-03-20 11:02**MOT test number** 158563934776**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm, cracked/perished and wearing outer edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm and wearing outer edge (5.2.3 (e))**MOT #10** 2019-04-04 14:59**MOT test number** 463078563723**Result** ✓ Passed**MOT #9** 2019-04-03 11:27**MOT test number** 655038338881**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 235/55/17 (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm and bulge in sidewall (5.2.3 (e))

**MOT #8** 2018-04-06 13:49**MOT test number** 674546527950**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules to calliper (3.6.B.4e)**Advice** Offside Rear tyre cracked, perished and worn inner edge**Advice** Offside Rear Brake hose has slight corrosion to ferrules to calliper (3.6.B.4e)**MOT #7** 2017-02-27 14:36**MOT test number** 294304634164**Result** ✓ Passed**Advice** Offside Rear tyre perished**Advice** Offside Front 3mm and bold inner and outer edges**MOT #6** 2017-02-24 12:28**MOT test number** 367798194594**Result** ✗ Failed**Advice** Offside Rear tyre perished**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 235/55/17 (4.1.E.1)**Advice** Offside Front 3mm and bold inner and outer edges**Fail** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #5** 2016-03-01 09:04**MOT test number** 484131852149**Result** ✓ Passed**Advice** Unable to fully inspect vehicle due to pans covering various areas of the vehicle**Advice** Offside Rear Inner Brake pad(s) wearing thin 2-2.5mm (3.5.1g)**Advice** Front Inner Brake pad(s) wearing thin unable to see (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #4** 2015-02-18 13:35**MOT test number** 706709345069**Result** ✓ Passed**MOT #3** 2014-02-24 10:37**MOT test number** 118485754090**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**MOT #2** 2013-02-22 11:26**MOT test number** 439513653094**Result** ✓ Passed**MOT #1** 2012-01-04 13:18**MOT test number** 169684102469**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
15 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-01-30
Last registration	2023-12-16
Complete history	See info



Registration #1	2009-01-30	15 mi
Registration #2	2012-01-04	26.662 mi
Registration #3	2013-02-22	36.038 mi
Registration #4	2014-02-24	46.842 mi
Registration #5	2015-02-18	58.220 mi
Registration #6	2016-03-01	69.182 mi
Registration #7	2017-02-24	76.760 mi
Registration #8	2017-02-27	76.761 mi
Registration #9	2018-04-06	89.662 mi
Registration #10	2019-04-03	99.523 mi
Registration #11	2020-05-20	109.384 mi
Registration #12	2021-06-17	119.245 mi
Registration #13	2022-07-14	129.106 mi
Registration #14	2023-08-11	138.967 mi
Registration #15	2024-09-08	148.828 mi
Registration #16	2025-10-05	158.689 mi
Registration #17	2026-11-02	168.550 mi
Registration #18	2027-11-29	178.411 mi
Registration #19	2028-12-26	188.272 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2142 mm
Height	1713 mm
Length	4628 mm
Wheel base	2774 mm
Kerb weight	1890 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	701175