



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H2 P/V CDTI
Colour	White
Year of manufacture	2014
Top speed	134 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 1.250 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	38.7 mpg
Consumption combined	34.9 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-11-01
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	13
Total items failed	0
MOT #7	2023-10-24 10:36
MOT test number	378119006436
Result	✓ Passed
Next expiry date	2024-11-01
MOT #6	2022-11-01 10:34
MOT test number	525809571235
Result	✓ Passed
MOT #5	2021-11-02 16:06
MOT test number	773506030308
Result	✓ Passed
MOT #4	2020-12-05 08:53
MOT test number	251961042770
Result	✓ Passed

**MOT #3** 2019-06-08 10:35**MOT test number** 670433667172**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #2** 2018-05-19 11:39**MOT test number** 821949937372**Result** ✓ Passed**Advice** Nearside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Outer sill damage**Advice** Central Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2017-06-17 09:50**MOT test number** 924220843370**Result** ✓ Passed**Advice** Central Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Play in steering rack inner joint(s) and o/s/f**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
1 November 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	1 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-07-29
Last registration	2023-10-24
Complete history	See info



Registration #1	2014-07-29	26 mi
Registration #2	2017-06-17	74.018 mi
Registration #3	2018-05-19	100.300 mi
Registration #4	2019-06-08	124.160 mi
Registration #5	2020-12-05	136.001 mi
Registration #6	2022-05-20	151.277 mi
Registration #7	2022-05-20	151.277 mi
Registration #8	2022-05-20	151.277 mi
Registration #9	2023-10-24	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2488 mm
Length	6198 mm
Kerb weight	1970 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	M9T -C073224 LWL