



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-12
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-04-18
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	25
Total items failed	11

MOT #19	2023-04-11 16:31
MOT test number	277112215819
Result	✓ Passed
Next expiry date	2024-04-18

MOT #18	2022-04-19 15:18
MOT test number	874221392158
Result	✓ Passed
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #17	2022-04-19 13:52
MOT test number	516742349537
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Fail	Nearside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #16** 2021-08-04 06:34**MOT test number** 613252279984**Result** ✓ Passed**Advice** Both sills corroded**MOT #15** 2021-08-04 06:34**MOT test number** 435805791321**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Both sills corroded**MOT #14** 2020-08-08 11:03**MOT test number** 153185920651**Result** ✓ Passed**MOT #13** 2019-08-07 10:08**MOT test number** 817238483925**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-08-07 10:08**MOT test number** 705363438050**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #11** 2018-07-07 09:23**MOT test number** 805153597902**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2018-07-07 09:23**MOT test number** 153709316722**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #9** 2017-07-14 06:21**MOT test number** 220971542558**Result** ✓ Passed**MOT #8** 2016-07-06 06:58**MOT test number** 926130855629**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #7** 2016-07-06 06:58**MOT test number** 116966957141**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #6** 2015-06-22 13:35**MOT test number** 376733275177**Result** ✓ Passed

**MOT #5** 2015-06-22 09:53**MOT test number** 819403875195**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-06-03 17:32**MOT test number** 765854054132**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Nearside front wiper blade is slightly worn**Advice** Brake pad(s) wearing thin (3.5.1g)**Notice** Rear exhaust section is corroded**MOT #3** 2013-06-04 17:10**MOT test number** 895965553162**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-11-20 12:00**MOT test number** 489675422416**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-11-20 12:00
MOT test number	699855422343
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL59DJD
Plate since	2019-03-29
Current registration	 GL59DJD
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-20
Last registration	2023-04-11
Complete history	See info



Registration #1	2009-11-20	7 mi
Registration #2	2012-11-20	50.616 mi
Registration #3	2013-06-04	61.466 mi
Registration #4	2014-06-03	66.042 mi
Registration #5	2015-06-22	70.387 mi
Registration #6	2015-06-22	70.387 mi
Registration #7	2016-07-06	80.075 mi
Registration #8	2016-07-06	80.075 mi
Registration #9	2017-07-14	90.398 mi
Registration #10	2018-07-07	100.660 mi
Registration #11	2019-06-20	111.017 mi
Registration #12	2019-06-20	111.017 mi
Registration #13	2019-06-20	111.017 mi
Registration #14	2019-06-20	111.017 mi
Registration #15	2019-06-20	111.017 mi
Registration #16	2019-06-20	111.017 mi
Registration #17	2019-06-20	111.017 mi
Registration #18	2019-06-20	111.017 mi
Registration #19	2019-06-20	111.017 mi
Registration #20	2019-06-20	111.017 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

BFS 076244