



General information

Make	VOLKSWAGEN
Model	SHARAN S TDI (115BHP)
Colour	Black
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	310 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.2 mpg
CO2 emission	196 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-06-17
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-05-17
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	28
Total items failed	8

MOT #17 2023-05-11 12:28**MOT test number** 215249626720**Result** ✓ Passed**Next expiry date** 2024-05-17

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2023-05-10 09:08**MOT test number** 438062094181**Result** ✗ Failed

- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Anti-roll bar attachment bracket/mounting fractured (5.3.3 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-05-18 16:07**MOT test number** 706623184335**Result** ✓ Passed

**MOT #14** 2021-11-08 18:50**MOT test number** 479215198022**Result** ✓ Passed**MOT #13** 2020-09-02 12:17**MOT test number** 807010221836**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2019-08-28 12:41**MOT test number** 870971851134**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

**MOT #11** 2019-08-15 10:09**MOT test number** 349233962445**Result** ✗ Failed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #10** 2018-08-04 09:56**MOT test number** 132270786077**Result** ✓ Passed**MOT #9** 2018-08-04 09:56**MOT test number** 409866159251**Result** ✗ Failed**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #8** 2017-06-13 13:49**MOT test number** 629719038436**Result** ✓ Passed**Advice** Both front tyres worn on edges**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #7** 2016-05-21 10:11**MOT test number** 852871569780**Result** ✓ Passed**Advice** Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #6** 2015-05-16 09:35**MOT test number** 779646635160**Result** ✓ Passed**MOT #5** 2014-05-31 11:11**MOT test number** 535441854173**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #4** 2013-05-31 12:33**MOT test number** 555411153154**Result** ✓ Passed**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside front brake juddering slightly (3.7.A.2b)**MOT #3** 2011-12-14 11:14**MOT test number** 155168541325**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-12-07 14:51
MOT test number	181321840383
Result	✓ Passed

MOT #1	2010-12-07 14:51
MOT test number	982211340398
Result	✗ Failed
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-06
Last registration	2023-05-11
Complete history	See info



Registration #1	2008-03-06	23 mi
Registration #2	2010-12-07	46.283 mi
Registration #3	2011-12-14	55.072 mi
Registration #4	2013-05-31	65.753 mi
Registration #5	2014-05-31	71.635 mi
Registration #6	2015-05-16	76.822 mi
Registration #7	2016-05-21	84.478 mi
Registration #8	2017-06-13	91.518 mi
Registration #9	2018-08-04	99.559 mi
Registration #10	2019-05-20	101.377 mi
Registration #11	2019-05-20	101.377 mi
Registration #12	2019-05-20	101.377 mi
Registration #13	2019-05-20	101.377 mi
Registration #14	2019-05-20	101.377 mi
Registration #15	2019-05-20	101.377 mi
Registration #16	2019-05-20	101.377 mi
Registration #17	2019-05-20	101.377 mi
Registration #18	2019-05-20	101.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1759 mm
Length	4634 mm
Wheel base	2841 mm
Kerb weight	1957 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BVK 026091