



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	White
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	17.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	134 BHP
Max. torque	343 Nm at 1.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	197 g/km
CO2 label	J



Internet history

Entry 1

Date	2021-08-09
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	6

MOT #10 2023-09-01 08:56

MOT test number 929466073943

Result ✓ Passed

Next expiry date 2024-09-01

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Nearside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9 2022-09-02 10:12

MOT test number 569308912430

Result ✓ Passed

**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Passenger seat(s) missing at time of test

MOT #8 2021-09-02 07:42

MOT test number 722020851164

Result ✓ Passed

**MOT #7**

2020-11-12 15:02

**MOT test number**

594656450734

**Result**

✓ Passed

**Advice**

Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #6**

2020-11-12 09:37

**MOT test number**

100747692851

**Result**

✗ Failed

**Fail**

Front Windscreen washer not working (3.5 (a))

**Advice**

Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail**

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice**

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Fail**

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #5**

2019-05-22 14:56

**MOT test number**

699313350225

**Result**

✓ Passed

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2019-05-20 10:02**MOT test number** 981593344897**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #3** 2018-05-17 13:15**MOT test number** 614067365950**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2017-05-09 08:18**MOT test number** 835573240818**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit wearing on edges (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit wearing on edges (4.1.E.1)**MOT #1** 2016-05-16 14:11**MOT test number** 120114802407**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
1 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	1 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-21
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2013-05-21	12 mi
Registration #2	2016-05-16	39.851 mi
Registration #3	2017-05-09	46.157 mi
Registration #4	2018-05-17	52.490 mi
Registration #5	2019-05-20	56.213 mi
Registration #6	2019-05-22	56.260 mi
Registration #7	2019-05-22	56.277 mi
Registration #8	2019-05-22	56.277 mi
Registration #9	2019-05-22	56.277 mi
Registration #10	2019-05-22	56.277 mi
Registration #11	2019-05-22	56.277 mi
Registration #12	2019-05-22	56.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2238 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

<b>Number of axles</b>	2
<b>Engine number</b>	D4CBC078473