





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D2 R-DESIGN NAV
Colour	Black
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/10



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2021-08-03
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	7
Total items failed	1

MOT #5	2020-07-31 15:17
MOT test number	365764646410
Result	✓ Passed
Next expiry date	2021-08-03

MOT #4		2020-07-31 12:43
MOT test	number	675523482848
Result		X Failed
MAJOR	Brake fluid contaminated (1.8 (a))	
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #3		2019-07-22 11:34
MOT test	number	556929970866
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/10



MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

802434736007

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 3/10



Tax & MOT check

Tax expired: 25 January 2021



X **MOT**

Expired: 3 August 2021

Tax status	Expired at 25 January 2021
Days left	1191 days too late
MOT expiry date	3 August 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2015-08-04
Last registration	2020-07-31
Complete history	See info



Registration #1	2015-08-04	29 mi
Registration #2	2018-07-23	42.509 mi
Registration #3	2019-07-22	58.353 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		n.m.

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1463 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	62 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	0/10