



General information

Make	VOLKSWAGEN
Model	SCIROCCO GTD
Colour	White
Year of manufacture	2010
Top speed	138 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 3

Date	2021-08-11
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk


Entry 2

Date	2021-08-10
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

Entry 1

Date	2021-05-23
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-19
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	37
Total items failed	7

MOT #132023-08-07 15:36

MOT test number957930439308

Result✓ Passed

Next expiry date2024-08-19

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge also (5.2.3 (e))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #12**

2023-08-07 08:35

**MOT test number**

547362327566

**Result****✗ Failed**

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge also (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing inner edge also (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #11**

2022-07-29 09:02

**MOT test number**

609428629570

**Result****✓ Passed**

- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10**

2021-08-20 04:59

**MOT test number**

429554471548

**Result****✓ Passed**

**MOT #9** 2021-08-20 04:59**MOT test number** 594192726887**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #8** 2020-10-08 08:44**MOT test number** 673798370488**Result** ✓ Passed**MOT #7** 2020-10-08 08:44**MOT test number** 218199242314**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2019-04-15 10:25**MOT test number** 880551615021**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing Inner side wall has small splits appearing (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2019-04-15 08:30**MOT test number** 470360023548**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing Inner side wall has small splits appearing (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-04-23 09:51**MOT test number** 286658991363**Result** ✓ Passed**Advice** Offside Front ride level sensor damaged**MOT #3** 2015-05-27 11:55**MOT test number** 716047645187**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2014-06-07 14:47
MOT test number	649728354161
Result	✓ Passed
Notice	Nail in nearside rear tyre
Notice	Rear tyres wearing inner edges

MOT #1	2013-06-01 15:47
MOT test number	999722653145
Result	✓ Passed
Notice	DPF fitted
Notice	N/s/r and o/s/f brakes slight binding
Notice	Rear tyres wearing on in side edges



Tax & MOT check

X

Untaxed

Tax expired:  
1 February 2024

✓

MOT

Expires:  
19 August 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	19 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-29
Current registration	 XXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-09
Last registration	2023-08-07
Complete history	<a href="#">See info</a>



Registration #1	2010-06-09	19 mi
Registration #2	2013-06-01	27.760 mi
Registration #3	2014-06-07	45.664 mi
Registration #4	2015-05-27	64.615 mi
Registration #5	2018-04-23	78.327 mi
Registration #6	2019-04-15	89.791 mi
Registration #7	2019-04-15	89.791 mi
Registration #8	2020-10-08	105.072 mi
Registration #9	2020-10-08	105.072 mi
Registration #10	2020-10-08	105.072 mi
Registration #11	2020-10-08	105.072 mi
Registration #12	2020-10-08	105.072 mi
Registration #13	2020-10-08	105.072 mi
Registration #14	2020-10-08	105.072 mi
Registration #15	2020-10-08	105.072 mi
Registration #16	2020-10-08	105.072 mi
Registration #17	2020-10-08	105.072 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CFG 121854