





report date: 2024-03-29

General information

| Make | VAUXHALL |
|---------------------|---------------------|
| Model | CORSA SE SE PREMIUM |
| Colour | Black |
| Year of manufacture | 2020 |
| Top speed | 108 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 74 BHP |
|----------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.199 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption combined | 53.3 mpg |
| CO2 emission | 93 g/km |
| CO2 label | А |



CarCheck.co.uk page 1/10



Internet history

Entry 2

| Date | 2021-07-23 |
|------|------------|
| | |

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

Entry 1

| Date | 2021-07-15 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date | 2025-02-02 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 2 |
| Failed MOT tests | 1 |
| Total advice items | 2 |
| Total items failed | 2 |

| MOT #3 | 2024-02-03 08:48 |
|--|------------------|
| MOT test number | 604484559380 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-02 |
| Advice Front Brake disc worn, but not excessively o/s and n/s (1.1.14 (a) (i)) | |

| MOT #2 | 2024-02-03 08:48 |
|--|---|
| MOT test number | 369769558556 |
| Result | ▼ Failed |
| Pass with rectification (ii)) | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Advice Front Brake disc worn, but not excessively o/s and n/s (1.1.14 (a) (i)) | |

| MOT #1 | 2023-02-03 10:07 |
|-----------------|------------------|
| MOT test number | 973025467076 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 2 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Е |
| First licence fee (12 months) | £ 165,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 4/10



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

Damage 2

| Damage 2 | |
|----------|--|
| Date | |
| Category | |



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | NE NE |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 011.1.6. | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2020-01-31 |
| Last registration | 2024-02-03 |
| Complete history | See info |



| Registration #1 | 2020-01-31 | 14 mi |
|-----------------|------------|-----------|
| Registration #2 | | 77,777 66 |
| Registration #3 | | 11.777 es |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 9.77 sc |
| Pogistration #6 | | |

Registration #6

More info >

CarCheck.co.uk page 9/10



Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 84% |
| Children | 86% |
| Pedestrian | 66% |
| Safety systems | 69% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| Width | 1960 mm |
|---------------------|---------|
| Height | 1433 mm |
| Length | 4060 mm |
| Max. allowed weight | 1550 kg |

Additional information

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | HM05-35748 |

CarCheck.co.uk page 10/10