



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V
Colour	Black
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-25
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-04-22
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	41
Total items failed	8

## MOT #14 2024-04-23 11:07

MOT test number 351595393261

Result ✓ Passed

Next expiry date 2025-04-22

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor** Front Lower Suspension component ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))
- Advice** Suspension arm corroded but not seriously weakened front and rear both sides (5.3.3 (b) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive sump plug (8.4.1 (a) (i))

## MOT #13 2022-12-10 09:32

MOT test number 462308928642

Result ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Suspension arm corroded but not seriously weakened all of them, front and rear (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #12** 2021-10-16 11:03**MOT test number** 923319443455**Result** ✓ Passed**MOT #11** 2020-09-02 10:03**MOT test number** 934698459164**Result** ✓ Passed**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Minor** Offside Rear Position lamp light intensity obviously reduced (4.2.3 (a) (i))**MOT #10** 2019-09-13 13:03**MOT test number** 363412238589**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Oil leak, but not excessive rhs of engine (8.4.1 (a) (i))**Advice** Oil leak, but not excessive ns of gearbox (8.4.1 (a) (i))**Advice** Front wheel arches show signs of touching but not seen on lock to lock**MOT #9** 2019-09-13 13:03**MOT test number** 334929407289**Result** ✗ Failed**Advice** Oil leak, but not excessive rhs of engine (8.4.1 (a) (i))**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))**Advice** Front wheel arches show signs of touching but not seen on lock to lock**Advice** Offside Rear Nail in tyre**Advice** Oil leak, but not excessive ns of gearbox (8.4.1 (a) (i))**Pass with rectification** Offside Headlamp aim too far to the right (4.1.2 (a))

**MOT #8**

2018-09-18 15:01

**MOT test number**

295428738891

**Result**

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Items removed from driver's view prior to test items removed from interior mirror
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7**

2018-09-18 12:18

**MOT test number**

363934143392

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Front Items removed from driver's view prior to test items removed from interior mirror
- Pass with rectification** Nearside Front Headlamp aim too far to the left (4.1.2 (a))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Offside Front Headlamp aim too far to the left (4.1.2 (a))

**MOT #6**

2017-09-19 07:39

**MOT test number**

896162642611

**Result**

✓ Passed

**MOT #5** 2017-09-18 12:29**MOT test number** 723339358623**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2016-09-13 09:01**MOT test number** 399191379502**Result** ✓ Passed**Advice** Exhaust system rusty**Advice** Offside front inner cv joint leaking grease**MOT #3** 2015-09-25 17:37**MOT test number** 679943123466**Result** ✓ Passed**MOT #2** 2014-11-07 14:33**MOT test number** 705521714358**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Both front tyres wearing on inner edges**Advice** Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)



MOT #1	2013-10-04 08:57
MOT test number	208497973247
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
22 April 2025

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	94
------------------	----

<b>MOT expiry date</b>	22 April 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VK60WHG</b>
Plate since	2019-06-29
Current registration	 <b>VK60WHG</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-18
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2010-10-18	11 mi
Registration #2	2013-10-04	39.757 mi
Registration #3	2014-11-07	51.990 mi
Registration #4	2015-09-25	65.380 mi
Registration #5	2016-09-13	74.240 mi
Registration #6	2017-09-18	82.753 mi
Registration #7	2017-09-19	82.754 mi
Registration #8	2018-09-18	93.495 mi
Registration #9	2019-09-18	104.236 mi
Registration #10	2020-09-18	115.000 mi
Registration #11	2021-09-18	125.764 mi
Registration #12	2022-09-18	136.528 mi
Registration #13	2023-09-18	147.292 mi
Registration #14	2024-04-23	158.056 mi
Registration #15		
Registration #16		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	4892 mm
Kerb weight	1851 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3

**Number of axles**

2

**Engine number**

CAA 082285