





report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S500
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	382 BHP
Max. torque	529 Nm at 2.800 rpm
Engine capacity	5.461 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.1 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.9 mpg
CO2 emission	283 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-02


Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-23
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	24
Total items failed	4

MOT #16		2023-08-24 15:50
MOT test	number	512517386822
Result		✓ Passed
Next expi	ry date	2024-08-23
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))		
Advice Nearside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #15 2023-08-15 08:53

MOT test number 237532443524

Result X Failed

Advice Nearside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Parking (secondary brake) on a single line braking system has no recorded effort at a wheel o/s ,n/s . not working. (1.3.1 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14 2022-08-15 10:14

MOT test number 568433812446

Result ✓ Passed

Advice Hydraulic leak, but not excessive (8.4.1 (a) (i))

MOT #13 2021-08-17 08:46

MOT test number 813671143756

Result ✓ Passed

MOT #12 2021-01-23 16:04

MOT test number 582552023637

MOT #11 2019-10-14 10:15

MOT test number 884697382881

Result
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10	2018-10-26 15:16
MOT test number	280411374233
Result	✓ Passed
MOT #9	2017-09-29 16:27
MOT test number	315522481669
Result	✓ Passed
MOT #8	2016-10-27 10:26
MOT test number	157729095193
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Engine covers and under tray's fitted, obscuring some item's.	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2015-10-29 15:06
MOT test number	397602464485
Result	✓ Passed
MOT #6	2014-10-21 16:07
MOT test number	675244294252
Result	√ Passed
Notice Diag light	

MOT #5	2014-10-15 14:38
MOT test number	778488484279
Result	X Failed
Fail Nearside Front brake caliper leaking (3.6.A.1) Notice Diag light	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Notice Diag light is on

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number
686962982237

Result

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2

MOT test number

716998651266

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Engine diag light is on

 MOT #1
 2010-04-23 14:14

 MOT test number
 983303110130

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner History	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

2000000	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	AIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-07-25
Last registration	2023-08-24
Complete history	See info



Registration #1	2007-07-25	26 mi
Registration #2	2010-04-23	39.166 mi
Registration #3	2011-09-15	47.993 mi
Registration #4	2012-10-08	59.060 mi
Registration #5	2013-10-21	66.930 mi
Registration #6	2014-10-15	74.208 mi
Registration #7	2014-10-21	74.419 mi
Registration #8	2015-10-29	82.492 mi
Registration #9	2016-10-27	89.801 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5206 mm
Wheel base	3165 mm
Kerb weight	1985 kg
Max. allowed weight	2545 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	27396130173934

CarCheck.co.uk page 13/13