



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 V70 D5 SE
Colour	Blue
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	209 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-10-16
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	34
Total items failed	8

MOT #18	2024-04-12 17:14
MOT test number	770715694583
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2024-04-06 09:19
MOT test number	943204167507
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Rear Service brake excessively binding (1.2.1 (f))
Advice	Offside Rear spare wheel fitted
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #16** 2023-04-12 09:24**MOT test number** 224568749724**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2022-04-05 15:17**MOT test number** 882304541397**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14** 2022-04-05 08:33**MOT test number** 262379552467**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**MOT #13** 2021-04-08 12:45**MOT test number** 597266051405**Result** ✓ Passed**Advice** Oil leak, but not excessive on under engine tray. (8.4.1 (a) (i))

**MOT #12**

2020-03-25 14:52

**MOT test number**

572389708090

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement forward (5.3.4 (a) (i))

**Advice** Parking brake\lever has limited reserve travel

**Advice** Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement forward (5.3.4 (a) (i))

**Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2019-03-14 11:42

**MOT test number**

889431407417

**Result**

✓ Passed

**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2018-04-03 11:08

**MOT test number**

581748196728

**Result**

✓ Passed

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2017-03-16 11:36

**MOT test number**

596909537432

**Result**

✓ Passed

**MOT #8** 2016-03-29 10:27**MOT test number** 518775888142**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-03-16 11:26**MOT test number** 295665875016**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6** 2014-03-19 12:30**MOT test number** 225758874066**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Underside fuel pipe clips missing

**MOT #5** 2013-04-04 11:37**MOT test number** 277774993070**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4** 2012-04-11 16:53**MOT test number** 386102502162**Result** ✓ Passed



MOT #3	2011-02-25 11:55
MOT test number	136576751096
Result	✓ Passed

MOT #2	2010-02-19 15:25
MOT test number	142700750457
Result	✓ Passed
<div><div>Notice</div>Ns rear tyre worn on outer edge</div>	

MOT #1	2009-02-17 16:32
MOT test number	762338049011
Result	✓ Passed
<div><div>Notice</div>Child seat fitted not allowing full inspection of adult belt</div> <div><div>Advice</div>Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
11 April 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	11 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SM55VKN
Plate since	2019-03-28
Current registration	SM55VKN
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-11-09
Last registration	2024-04-12
Complete history	<a href="#">See info</a>



Registration #1	2005-11-09	26 mi
Registration #2	2009-02-17	49.221 mi
Registration #3	2010-02-19	65.583 mi
Registration #4	2011-02-25	82.551 mi
Registration #5	2012-04-11	96.506 mi
Registration #6	2013-04-04	106.125 mi
Registration #7	2014-03-19	113.673 mi
Registration #8	2015-03-16	121.689 mi
Registration #9	2016-03-29	128.248 mi
Registration #10	2017-03-16	133.198 mi
Registration #11	2018-03-29	138.148 mi
Registration #12	2019-03-29	143.098 mi
Registration #13	2020-03-29	148.048 mi
Registration #14	2021-03-29	153.000 mi
Registration #15	2022-03-29	157.950 mi
Registration #16	2023-03-29	162.900 mi
Registration #17	2024-03-29	167.850 mi
Registration #18	2025-03-29	172.800 mi
Registration #19	2026-03-29	177.750 mi
Registration #20	2027-03-29	182.700 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1427 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	291390