



report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ZETEC TDCI
Colour	Black
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	47.9 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-06-12
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-16
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	38
Total items failed	14

MOT #19	2024-02-19 10:25
MOT test number	993472796181
Result	✓ Passed
Next expiry date	2025-03-16

MOT #18	2024-02-16 17:28
MOT test number	173758560178
Result	✗ Failed
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #17	2023-03-17 11:54
MOT test number	261714167526
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #16**

2023-03-16 15:20

MOT test number

632142644307

Result

✗ Failed

- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15

2022-02-04 15:41

MOT test number

724705247916

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14

2021-01-19 08:39

MOT test number

793016782968

Result

✓ Passed

- Advice** Road wheel slightly distorted Offside rear Nearside front (5.2.2 (c) (i))
- Advice** Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Both front tyres worn slightly on inner edges
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both rear outer subframe bushes (5.3.4 (a) (i))
- Advice** Slight corrosion on exhaust rear section

**MOT #13** 2020-01-15 14:07**MOT test number** 880786315332**Result** ✓ Passed**Advice** Slight corrosion on exhaust rear silencer**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #12** 2020-01-15 09:25**MOT test number** 438008175482**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Slight corrosion on exhaust rear silencer**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #11** 2019-01-22 12:24**MOT test number** 744672574994**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Light corrosion on exhaust rear silencer**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #10** 2019-01-22 08:48**MOT test number** 828264501161**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Light corrosion on exhaust rear silencer**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #9** 2018-01-11 12:36**MOT test number** 745447115879**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Light corrosion on exhaust rear silencer**MOT #8** 2018-01-11 08:31**MOT test number** 377199144672**Result** ✗ Failed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Light corrosion on exhaust rear silencer**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #7** 2017-01-16 09:27**MOT test number** 128670768935**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Light corrosion on exhaust rear silencer

**MOT #6** 2016-01-14 09:02**MOT test number** 869186367110**Result** ✓ Passed**Advice** Offside front tyre worn on inner edge void of tread**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Near side rear tyre worn on inner edge void of tread**MOT #5** 2015-01-13 09:59**MOT test number** 567163615066**Result** ✓ Passed**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2015-01-13 09:59**MOT test number** 817563415095**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #3** 2014-01-14 11:26**MOT test number** 449924614056**Result** ✓ Passed**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2014-01-14 08:54**MOT test number** 705324414084**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #1	2013-01-26 09:30
MOT test number	436816423089
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-29
Last registration	2024-02-19
Complete history	See info



Registration #1	2010-01-29	9 mi
Registration #2	2013-01-26	26.835 mi
Registration #3	2014-01-14	32.913 mi
Registration #4	2014-01-14	32.914 mi
Registration #5	2015-01-13	41.415 mi
Registration #6	2016-01-14	49.429 mi
Registration #7	2017-01-16	57.669 mi
Registration #8	2018-01-11	65.132 mi
Registration #9	2018-01-11	65.132 mi
Registration #10	2019-01-22	72.096 mi
Registration #11	2019-01-22	72.096 mi
Registration #12	2019-01-22	72.096 mi
Registration #13	2019-01-22	72.096 mi
Registration #14	2019-01-22	72.096 mi
Registration #15	2019-01-22	72.096 mi
Registration #16	2019-01-22	72.096 mi
Registration #17	2019-01-22	72.096 mi
Registration #18	2019-01-22	72.096 mi
Registration #19	2019-01-22	72.096 mi
Registration #20	2019-01-22	72.096 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1155 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

9E23153